

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005292/R1VF3N2**Date:** 13/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30759219000

Claimant Vehicle No : FBF9969R**Insured Vehicle No :** GBH9238G

Date of Loss: 05/10/2020

Nature of Claim: TP

Claim No: SNM20D203743/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBF9969R**

Make & Model: HONDA ANF125MSS A, 125cc

Engine No: NF125MME5001427

Reg. Date: 15/02/2012 (Man. Year: 2010)

Chassis No: NF125MM5001427

Colour: Blue

Odometer: 59344 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size:

80/90-17

Front Left Side: Dunlop 3 mm

Rear Left Side:

Dunlop 3 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,441.20	2,441.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	430.00	270.00	38.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,141.20	2,871.20	270.00	8.60
Approved Total (Overridden) (\$\$)		2,600.00		
Nett Amount (\$\$)	3,141.20	2,600.00	541.20	17.23

INSPECTION

Date of Assignment: 29/04/2021

Date Inspected: 29/04/2021 Inspected At:

Chua Chu Kang Motorcycle Trading (HQ)
27-A JURONG PORT ROAD #01-20
Singapore 619101

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Oct 2021)	
Parts:	N/A	HONDA ANF125MSS A 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF9969R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cracked	95.00 FL	*95.00 FL
2	1		*HEADLAMP COVER	Cracked	65.00 FL	*65.00 FL
3	1		*METER COVER	Cracked	68.00 FL	*68.00 FL
4	1		*SET MIRROR	Cracked	45.00 FL	*45.00 FL
5	1		*HANDLE	Bent	95.00 FL	*95.00 FL
6	1		*HANDLE BRACKET	Bent	84.00 FL	*84.00 FL
7	1		*SET LH FRONT OUTSIDE COVER	Scratched	165.00 FL	*165.00 FL
8	1		*SET RH FRONT OUTSIDE COVER	Cracked	165.00 FL	*165.00 FL
9	1		*FRONT CENTRE COVER	Cracked	68.00 FL	*68.00 FL
10	1		*FRONT MUDGUARD	Scratched	95.00 FL	*95.00 FL
11	1		*SET FRONT FORK	Bent	595.00 FL	*595.00 FL
12	1		*SET RIM	Scratched	365.00 FL	*365.00 FL
13	1		*FOOTREST BRACKET	Bent	67.00 FL	*67.00 FL
14	1		*GEAR PEDAL	Bent	58.00 FL	*58.00 FL
15	1		*RH TAIL SEAT BOTTOM COVER	Cracked	168.00 FL	*168.00 FL
16	1		*FRONT BASKET	Bent	28.00 FS	*28.00 FS
17	1		*REAR BOX BRACKET	Bent	65.00 FS	*65.00 FS
18	1		*REAR BOX	Scratched	185.00 FS	*185.00 FS
19	1		*IU	Cracked	185.00 FS	*185.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,661.00	2,661.00
- List Item Discount on L Items 10.00/10.00% (S\$)	219.80	219.80
Total Parts (S\$)	2,441.20	2,441.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGE	New	50.00	30.00
2	CHASSIS REPAIR	New	350.00	200.00
3	WORKMANSHIP	New	300.00	200.00
Gross Labour Cost (\$)			700.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >