

Date: 28.04.2021
Vehicle No: SMU4299U
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72106542
Reg.Year: 2020

Third Party Insurer: INDIA
Third Party Veh No: SLM4404G
Date of Accident: 27.04.2021

*Not working
Repairing B & paint
4-5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$1,217.00
2	REAR TAILGATE INNER TRIM BOARD	1		\$370.00
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>nn</i> \$75.00
4	REAR TAILGATE "HYBRID" EMBLEM	1		<i>nn</i> \$65.00
5	REAR WINDSCREEN RUBBER <i>ndy</i>	1		<i>nn</i> \$120.00
6	REAR TAILGATE WEATHERSTRIP	1		\$168.50
7	REAR BUMPER	1		\$1,189.00
8	REAR BUMPER CHROME	1		<i>nn</i> \$178.00
9	END PANEL	1		\$560.80
10	END PANEL TOP COVER	1		\$155.50
SUB TOTAL				\$4,098.80
LESS 20%				-\$819.76
PARTS TOTAL				\$3,279.04

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>nn</i> \$60.00
2	REAR BUMPER CLIPS	1		\$60.00
3	REAR BUMPER REVERSE SENSOR	1		\$250.00
4	REAR END PANEL TOP COVER CLIPS	1		<i>nn</i> \$35.00
S/N TOTAL				\$405.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX REAR ACCIDENT AREA.

To confirm
\$800.00 ?

LABOUR CHARGES TO SUPPLY PAINT FOR REAR ACCIDENT AREA.

\$800.00 *400*

LABOUR CHARGES TO REMOVE AND REFIX REAR WINDSCREEN GLASS.

\$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM.

\$120.00 *60*

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR.

\$100.00 ?

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 8868 | Fax: (+65) 6452 9223



Date: 28.04.2021
Vehicle No: SMU4299U
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72106542
Reg.Year: 2020

Third Party Insurer: INDIA
Third Party Veh No: SLM4404G
Date of Accident: 27.04.2021

TO APPLY ANTI-RUST.

\$150.00 301

TO DIAGNOSIS FAULTY CODE & RESET MEMORY.

\$150.00 7

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 201

LABOUR TOTAL \$2,370.00

Vic TOTAL \$6,054.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1212 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

