

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5154X

AAD2104-125

*Not Authorised**U/Lmp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

27 APR 2021

SHC5154X

VF1ABL15AUC276543

RENAULT

LATITUDE

24/04/2021

EQ

14/01/2014

PART**LIST**

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH
- 1 ABSORBER REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel)TRIM
- 1 BOOT REAR
- 1 BOOT LOCK
- 1 BOOT LOCK CATCH
- 1 BOOT FINISHER
- 1 BOOT WEATHERSTRIP
- 1 BOOT STRUT LH
- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT BADGE 'RENAULT'

\$	Bu	561.70	—
\$	nd/cmt	411.90	✓
\$	cmt	16.60	—
\$	Sn	16.60	X
\$	Dfr	98.10	—
\$	Sn	82.10	X
\$	Sn	59.80	X
\$	Sn	80.80	X
\$	Sn	54.20	X
\$	R	1,933.20	X
\$	Sn	275.40	X
\$	Sn	217.30	X
\$	R	547.80	✓
\$	Dfr	114.50	—
\$	R	114.50	—
\$	R	745.80	—
\$	nd	404.56	—
\$	R	1,677.20	—
\$	nd	246.60	—
\$	R	41.70	X
\$	Sn	344.70	X
\$	Sn	178.20	502m
\$	Sn	145.10	X
\$	Sn	145.10	X
\$	R	254.20	X
\$	R	254.20	X
\$	Sn	82.40	—

TOTAL
TOTAL PARTS

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2104-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6257 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHCS154X

1 BOOT BADGE	\$	95.80	✓
1 BOOT REFLECTOR LAMP LH	\$	277.70	X
1 BOOT REFLECTOR LAMP RH	\$	277.70	X
1 TAILLAMP LH	\$	401.40	X
1 TAILLAMP RH	\$	401.40	X
1 EXHAUST REAR	\$	5,263.60	X
1 EXHAUST CAP REAR	\$	125.40	X

	\$	15,947.26
10%	\$	1,594.73
	\$	14,352.53

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 EXHAUST MOUNTING REAR	\$	17.82	X
1 LICENSE PLATE WITH HOLDER FRT	\$	120.00	X
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL	\$	1,509.82	
TOTAL PARTS	\$	15,862.35	

LABOUR

To Remove And Refit Rear Big and Small W/Screen
Glass To Facilitate Bodywork Repair.

\$ 300.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 6601

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 3,000.00 6001

Trans-cab Auto Services Pte Ltd

AAD2104-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5154X

To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	7,880.00	
Over All Total	\$	38,094.89	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(LUMP SUM)**Repair Days****10 DAYS****5 days**