

ASS. REC. BY:

REF:

C72 / 210033071Kt

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

18 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 7284X

Yr Regn:

05, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S

6A

NV350

c.c

2488

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

2485

T/Radio:

Insured / Std / NI / NA

Eng/No:

117463

C/No:

JNITC 28268 0051 PTF

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

27/4/21

D.O.I.

30/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 1st off

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

part by part \$18312, 18days
red: 3790;17%

22102

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

18

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

PC7284X
TP/CHINA**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 29 Apr 2021)**Parts:** N/A NISSAN NV350 2.5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for PC7284X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC FRT BUMPER	Ry	0.00	0.00	*320.00F ✓
2	1		*1 PC FRT BUMPER RH SIDE RETAINER	117	0.00	0.00	*85.00F ✓
3	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH	117	0.00	0.00	*90.00F ✓
4	1		*1 PC FRT BUMPER REINFORCEMENT		0.00	0.00	*290.00F ?
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE		0.00	0.00	*395.00F ?
6	1		*6 PCS FRT BUMPER CLIPS @2/PC	117	0.00	0.00	*12.00F ✓
7	1		*1 PC FRT BUMPER RH BRACKET	117	0.00	0.00	*70.00F ✓
8	1		*1 PC RH HEADLAMP	130	0.00	0.00	*260.00F ✓
9	1		*1 PC FRT RH CORNAL PANEL	Ry	0.00	0.00	*220.00F ✓
10	1		*1 PC FRT GRILLE	117	0.00	0.00	*300.00F ✓
11	1		*1 PC FRT GRILLE LOGO	117	0.00	0.00	*65.00F ✓
12	1		*6 PCS FRT GRILLE CLIPS @2/PC	117	0.00	0.00	*12.00F ✓
13	1		*1 PC FRT PANEL	Ry	0.00	0.00	*550.00F ✓
14	1		*1 PC FRT PANEL INNER LOWER PANEL		0.00	0.00	*350.00F ?
15	1		*1 PC FRT WINDSCREEN GLASS WITH MOULDING	CM 117	0.00	0.00	*600.00F ✓
16	1		*1 PC FRT WIPER GARNISH	CM 117	0.00	0.00	*140.00F ✓
17	1		*1 PC FRT WIPER LINKAGE		0.00	0.00	*250.00F ✓
18	1		*1 PC FRT WIPER MOTOR		0.00	0.00	*260.00F ?
19	1		*1 PC ENGINE TURBO COOLER RH		0.00	0.00	*1,500.00F ?
20	1		*1 PC ENGINE TURBO COOLER COVER		0.00	0.00	*95.00F ?
21	1		*1 PC DASHBOARD FACIAL	117	0.00	0.00	*720.00F ✓
22	1		*1 PC DASHBOARD CENTRE LOWER GARNISH COVER	117	0.00	0.00	*220.00F ✓
23	1		*1 PC METER ASSY		0.00	0.00	*920.00F ?
24	1		*1 PC BRAKE BOOSTER		0.00	0.00	*1,030.00F ?
25	1		*1 PC BRAKE MUSTER PUMP		0.00	0.00	*220.00F ?
26	1		*1 PC BRAKE BOOSTER BRACKET		0.00	0.00	*260.00F ?
27	1		*1 PC STEERING WHEEL SHAFT COVER	117	0.00	0.00	*125.00F ✓
28	1		*1 PC HORN	117	0.00	0.00	*68.00F ✓
29	1		*1 PC BRAKE MUSTER PUMP/BOOSTER OIL PIPE		0.00	0.00	*60.00F ?
30	1		*1 PC BRAKE MUSTER PUMP OIL PIPE SMALL		0.00	0.00	*65.00F ?
31	1		*1 PC REAR BUMPER	Ry	0.00	0.00	*290.00F ✓
32	1		*1 PC REAR BUMPER CENTRE STEP PANEL	Ry	0.00	0.00	*135.00F ✓
33	1		*2 PCS REAR BUMPER SIDE RETAINERS @12/PC	CM 117	0.00	0.00	*24.00F ✓
34	1		*8 PCS REAR BUMPER CLIPS @2/PC	117	0.00	0.00	*16.00F ✓
35	1		*1 PC REAR END PANEL OUTER	Ry	0.00	0.00	*145.00F ✓
36	1		*1 PC REAR END PANEL INNER		0.00	0.00	*260.00F ?
37	1		*1 PC REAR END PANEL INNER TOP BEAM		0.00	0.00	*55.00F ?
38	1		*1 PC TAILGATE	Ry	0.00	0.00	*1,500.00F ✓
39	1		*1 PC TAILGATE LOGO	117	0.00	0.00	*55.00F ✓
40	1		*1 PC TAILGATE EMBLEM (NV350)	117	0.00	0.00	*65.00F ✓
41	1		*1 PC TAILGATE INNER LOCK	117	0.00	0.00	*210.00F ✓
42	1		*1 PC TAILGATE INNER RUBBER		0.00	0.00	*125.00F ?
43	1		*1 PC LH TAILLAMP		0.00	0.00	*110.00F ?

F=Franchise part.

Total Parts (\$\$) **12,542.00**Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 LTR BRAKE OIL	20.00
2	1	1 PC ERP BRACKET	20.00
3	1	1 PC FRT NUMBER PLATE	15.00
4	1	1 PC FRT WINDSCREEN GLASS GUM	40.00
5	1	1 PC REAR WINDSCREEN GLASS GUM	40.00
6	1	1 PC STICKER - 70KM/H	10.00
7	1	1 PC TAILGATE EMERGENCY DOOR STICKER	45.00
8	1	1 SET REVERSE SENSOR	200.00
Sub Total (S\$)			390.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING	New	50.00
2	REMOVE & REFIX FRT WINDSCREEN GLASS	New	100.00
3	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00
4	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00
5	REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	New	230.00
6	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT WIPER ASSY,CORNAL PANEL,TO CUT,WELD & RENEW FRT PANEL,FRT FIRE WALL,TO KNOCK & REPAIR FRT FLOOR BOARD PANEL & REALIGN THE SAME	New	1,400.00
7	REMOVE & REFIX ENGINE TURBO COOLER,REMOVE & REFIX BRAKE MUSTER PUMP & BRACKET,BOOSTER,PIPE & HOSE,HAND BRAKE ASSY AND CHECK BARKE SYSTEM	New	250.00
8	PUTTY & RESPRAY ON FRT BUMPER,FRT CORNAL PANEL,FRT PANEL,FRT INNER PANEL,FRT FLOOR BOARD PANEL,FRT RH DOOR & ALL FRT AFFECTED AREAS	New	1,200.00
9	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE,LOCK ASSY,REAR WIPER ASSY,THIRD BRAKE LIGHT,TO CUT,WELD & RENEW REAR END PANEL,REAR END PANEL INNER,TO STRAIGHTEN,KNOCK & REPAIR REAR LH CHASSIS,REAR FLOOR BOARD PANEL,REAR BOTH FENDERS,REAR LH TAILLAMP PANEL & REALIGN THE SAME	New	1,200.00
10	REMOVE & REFIX SEAT,CARPET,GARNISH,ETC	New	200.00
11	REMOVE & REFIX REAR EXHAUST & CHECK LEAKING	New	80.00
12	PUTTY & RESPRAY ON REAR BOTH SIDE PANELS,TAILGATE,REAR END PANEL OUTER & INNER,REAR FLOOR BOARD PANEL,REAR BUMPER & ALL REAR AFFECTED AREAS	New	1,300.00
13	TO RUSTPROOFING	New	150.00
14	TO REWRITE ADVERTISEMENT	New (B.11)	300.00
Gross Labour Cost (S\$)			6,660.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(SJG3511S)
Policy No:	DMPCSNA00185572006	Date of Loss:	27/04/2021
Vehicle Reg. No.:	PC7284X	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	TOH CHEE KWANG
Driver (TP):	LIM HENG SENG HENRY	Vehicle Reg. Date:	24/05/2018
Make/Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1TC2E26Z0051974
Vehicle Colour:	SILVER		
Engine No:	YD25017695B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not authorized
Repair B4 pain
18 days*

COST OF CLAIMS	Amount
Parts	12,542.00
Miscellaneous Items	390.00
Labour	6,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,592.00
+ GST 7.00% (S\$)	1,371.44
Nett Amount (S\$)	20,963.44

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/04/2021 17:59 (SGT)
Date of Accident	27/04/2021 17:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLE TWDS BKE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC7284X
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MAMRE OAKS LIMITED
Company Reg No	2XXXXX053M
Email Address	joseph.lim@mamreoaks.sg
Mobile Phone No	(Phone) +65-90622515
Alternative Phone No	+65-90622515

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Nv350
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	2488

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5099867469-02
Cover Note Number	-

DRIVER

Name of Driver	LIM HENG SENG HENRY
NRIC No	SXXXX078A

SKETCH PLAN

road shoulder

516 TWDs BKE

A = PC7284X

B = SJG35115 (Alone)
Toh Chee Kwang
S157 0232 Z

C = YN6805K (Alone)
China National

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: T/20210428/2003

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()