



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax : +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

|                     |                           |                       |            |
|---------------------|---------------------------|-----------------------|------------|
| Claim Type:         | OD (OWN DAMAGE)           | Ref. No:              | YN8716X    |
| Policy No:          | DMCVSNW00066832000        | Date of Loss:         | 23/03/2021 |
| Vehicle Reg. No.:   | <b>YN8716X</b>            | Driveable?            |            |
| Driver Age/Info:    | / MALE                    | Party At Fault:       | UNKNOWN    |
| TP Injury Involved? | NO                        | Third Party Involved? | YES        |
| Insured/Claimant:   | MAY ENGINEERING PTE. LTD. |                       |            |

|                 |                            |                    |                   |
|-----------------|----------------------------|--------------------|-------------------|
| Make/Model:     | ISUZU NPR85UH5A, 3.0 D (M) | Vehicle Reg. Date: | 25/08/2015        |
| Vehicle Colour: | WHITE                      |                    |                   |
| Engine No:      | 4JJ11Z1889                 | Chassis No:        | JAANPR85HF7100422 |
| Odometer:       | 0 KM                       |                    |                   |

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 28

DEAR KAH LEONG

AS SPOKEN, CUSTOMER WAS SUBMIT FOR OD CLAIMS SINCE 25/3/2021 BUT WE ARE LOOKING FOR THE CABIN HEAD PART PRICE BEFORE WE SUBMIT THE MERIMEN SYSTEM.

Remarks: NOW WE GOT THE CABIN HEAD AND THE PART PRICE SUBMITTED THRU MERIMEN AND AUDATEX.

KINDLY ARRANGE FOR THE SURVEY.

THANK YOU.

Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)

## COST OF CLAIMS

|                     | Amount    |
|---------------------|-----------|
| Parts               | 55,391.00 |
| Miscellaneous Items | 0.00      |
| Labour              | 4,410.00  |
| Paintwork Labour    | 1,226.00  |
| Towing              | 0.00      |

|                   |           |
|-------------------|-----------|
| Gross Total (S\$) | 61,027.00 |
| + GST 7.00% (S\$) | 4,271.89  |
| Nett Amount (S\$) | 65,298.89 |

This claim is handled by: SOO LEONG KEAT

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 29 Apr 2021)

**Parts:** N/A ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Goldbell Engineering Pte Ltd/YN8716X/29/04/2021 15:03

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars           | %Disc | %Depr |       | Amount         |
|-----|-----|----------|-----------------------|-------|-------|-------|----------------|
| 1   | 1   | NA       | *AIR INTAKE HOSE      | 0.00  | 0.00  | CRA   | *180.00 F ✓    |
| 2   | 1   | NA       | *CAB BODY CONTROL     | 0.00  | 0.00  | BT    | *350.00 F ✓    |
| 3   | 1   | NA       | *CABIN HEAD           | 0.00  | 0.00  | BT    | *19,800.00 F ✓ |
| 4   | 1   | NA       | *COMPRESSOR           | 0.00  | 0.00  | X SVC | *580.00 F ✓    |
| 5   | 1   | NA       | *CONDENSER            | 0.00  | 0.00  | BT    | *1,300.00 F ✓  |
| 6   | 1   | NA       | *CTR FRT PANEL STRUT  | 0.00  | 0.00  | BT    | *750.00 F ✓    |
| 7   | 1   | NA       | *FRONT BUMPER         | 0.00  | 0.00  | de    | *360.00 F ✓    |
| 8   | 1   | NA       | *FRONT MANUFACT BADGE | 0.00  | 0.00  | nec   | *320.00 F ✓    |
| 9   | 1   | NA       | *FRONT NUMBER PLATE   | 0.00  | 0.00  | BT    | 35 *-F ✓       |
| 10  | 1   | NA       | *FRONT PANEL CPL      | 0.00  | 0.00  | RUC   | *1,150.00 F ✓  |
| 11  | 1   | NA       | *FRONT PANEL TRIM     | 0.00  | 0.00  | de    | *350.00 F ✓    |
| 12  | 1   | NA       | *FRONT ROOF FRAME     | 0.00  | 0.00  | BT    | *350.00 F ✓    |
| 13  | 1   | NA       | *FRONT TORSION BAR    | 0.00  | 0.00  | BT    | *540.00 F ✓    |
| 14  | 1   | NA       | *GRILLE               | 0.00  | 0.00  | MIS   | *256.00 F ✓    |
| 15  | 1   | NA       | *L/CVR PANEL SEAL KIT | 0.00  | 0.00  | nec   | *120.00 F ✓    |
| 16  | 1   | NA       | *L/D-MIRROR BRACKET   | 0.00  | 0.00  | MIS   | *85.00 F ✓     |
| 17  | 1   | NA       | *L/DOOR LOCK CYLINDER | 0.00  | 0.00  | JAM   | *150.00 F ✓    |
| 18  | 1   | NA       | *L/DOOR MIRROR        | 0.00  | 0.00  | MIS   | *130.00 F ✓    |
| 19  | 1   | NA       | *L/DOOR MIRROR ARM    | 0.00  | 0.00  | MIS   | *120.00 F ✓    |
| 20  | 1   | NA       | *L/DOOR OUTER HANDLE  | 0.00  | 0.00  | X SVC | *130.00 F ✓    |
| 21  | 1   | NA       | *L/DOOR SEAL          | 0.00  | 0.00  | nec   | *80.00 F ✓     |
| 22  | 1   | NA       | *L/DOOR STRIKER       | 0.00  | 0.00  | nec   | *80.00 F ✓     |
| 23  | 1   | NA       | *L/F BUMPER BRACKET   | 0.00  | 0.00  | BT    | *165.00 F ✓    |
| 24  | 1   | NA       | *L/F BUMPER GUARD     | 0.00  | 0.00  | BT    | *450.00 F ✓    |
| 25  | 1   | NA       | *L/F CORNER PANEL     | 0.00  | 0.00  | CRA   | *280.00 F ✓    |
| 26  | 1   | NA       | *L/F CTR CAB BRACKET  | 0.00  | 0.00  | BT    | *280.00 F ✓    |
| 27  | 1   | NA       | *L/F DOOR CHECK       | 0.00  | 0.00  | X SVC | *120.00 F ✓    |
| 28  | 1   | NA       | *L/F DOOR FOIL COVER  | 0.00  | 0.00  | X SVC | *120.00 F ✓    |
| 29  | 1   | NA       | *L/F DOOR FRAME SEAL  | 0.00  | 0.00  | nec   | *280.00 F ✓    |
| 30  | 1   | NA       | *L/F DOOR TRIM        | 0.00  | 0.00  | CRA   | *230.00 F ✓    |
| 31  | 1   | NA       | *L/F DOOR WINDOW      | 0.00  | 0.00  | GRD   | *580.00 F ✓    |
| 32  | 1   | NA       | *L/F HEADLAMP BRACKET | 0.00  | 0.00  | BT    | *120.00 F ✓    |
| 33  | 1   | NA       | *L/F INN DOOR HANDLE  | 0.00  | 0.00  | X SVC | *130.00 F ✓    |
| 34  | 1   | NA       | *L/F INN WINDOW MLDG  | 0.00  | 0.00  | nec   | *130.00 F ✓    |
| 35  | 1   | NA       | *L/F UPP TORSION BAR  | 0.00  | 0.00  | BT    | *450.00 F ✓    |
| 36  | 1   | NA       | *L/F WINDOW CHANNEL   | 0.00  | 0.00  | de    | *150.00 F ✓    |

Goldbell Engineering Pte Ltd/YN8716X/29/04/2021 15:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

| No. | Qty | Part No. | Particulars           | %Disc | %Depr | Amount          |
|-----|-----|----------|-----------------------|-------|-------|-----------------|
| 37  | 1   | NA       | *L/F WINDOW REGULATOR | 0.00  | 0.00  | X SVC *280.00 F |
| 38  | 1   | NA       | *L/F WIPER ARM        | 0.00  | 0.00  | bt *125.00 F    |
| 39  | 1   | NA       | *L/F WIPER BLADE      | 0.00  | 0.00  | cut *60.00 F    |
| 40  | 1   | NA       | *L/HEADLAMP BRACKET   | 0.00  | 0.00  | X SVC *130.00 F |
| 41  | 1   | NA       | *L/INN DOOR LOCK      | 0.00  | 0.00  | JAM *120.00 F   |
| 42  | 1   | NA       | *L/INN IMPACT DAMPER  | 0.00  | 0.00  | bt *540.00 F    |
| 43  | 1   | NA       | *L/INN WHEELHOUSE CVR | 0.00  | 0.00  | de *380.00 F    |
| 44  | 1   | NA       | *L/LOWER DOOR HINGE   | 0.00  | 0.00  | bt *80.00 F     |
| 45  | 1   | NA       | *L/LOWER H-LAMP MLDG  | 0.00  | 0.00  | SCR *130.00 F   |
| 46  | 1   | NA       | *L/POSITION LAMP      | 0.00  | 0.00  | CRA *350.00 F   |
| 47  | 1   | NA       | *L/R LOCKING          | 0.00  | 0.00  | JAM *350.00 F   |
| 48  | 1   | NA       | *L/SIDE FRAME         | 0.00  | 0.00  | bt *2,580.00 F  |
| 49  | 1   | NA       | *L/SIDE MEMBER        | 0.00  | 0.00  | bt *280.00 F    |
| 50  | 1   | NA       | *L/UPPER DOOR HINGE   | 0.00  | 0.00  | bt *80.00 F     |
| 51  | 1   | NA       | *L/WIPER SHAFT        | 0.00  | 0.00  | bt *250.00 F    |
| 52  | 1   | NA       | *LEFT FRONT DOOR      | 0.00  | 0.00  | BUC *1,250.00 F |
| 53  | 1   | NA       | *LEFT HEADLAMP ASSY   | 0.00  | 0.00  | CRA *420.00 F   |
| 54  | 1   | NA       | *LOWER FRONT PANEL    | 0.00  | 0.00  | bt *450.00 F    |
| 55  | 1   | NA       | *R/CVR PANEL SEAL KIT | 0.00  | 0.00  | ACC *120.00 F   |
| 56  | 1   | NA       | *R/D-MIRROR BRACKET   | 0.00  | 0.00  | MIS *85.00 F    |
| 57  | 1   | NA       | *R/DOOR LOCK CYLINDER | 0.00  | 0.00  | JAM *150.00 F   |
| 58  | 1   | NA       | *R/DOOR MIRROR        | 0.00  | 0.00  | MIS *130.00 F   |
| 59  | 1   | NA       | *R/DOOR MIRROR ARM    | 0.00  | 0.00  | MIS *120.00 F   |
| 60  | 1   | NA       | *R/DOOR SEAL          | 0.00  | 0.00  | ACC *80.00 F    |
| 61  | 1   | NA       | *R/DOOR STRIKER       | 0.00  | 0.00  | JAM *80.00 F    |
| 62  | 1   | NA       | *R/F BUMPER BRACKET   | 0.00  | 0.00  | bt *165.00 F    |
| 63  | 1   | NA       | *R/F CORNER PANEL     | 0.00  | 0.00  | CRA *280.00 F   |
| 64  | 1   | NA       | *R/F CTR CAB BRACKET  | 0.00  | 0.00  | bt *280.00 F    |
| 65  | 1   | NA       | *R/F DOOR CHECK       | 0.00  | 0.00  | JAM *120.00 F   |
| 66  | 1   | NA       | *R/F DOOR FOIL COVER  | 0.00  | 0.00  | X SVC *120.00 F |
| 67  | 1   | NA       | *R/F DOOR FRAME SEAL  | 0.00  | 0.00  | ACC *280.00 F   |
| 68  | 1   | NA       | *R/F DOOR TRIM        | 0.00  | 0.00  | CRA *230.00 F   |
| 69  | 1   | NA       | *R/F DOOR WINDOW      | 0.00  | 0.00  | BRO *580.00 F   |
| 70  | 1   | NA       | *R/F HEADLAMP BRACKET | 0.00  | 0.00  | X SVC *120.00 F |
| 71  | 1   | NA       | *R/F INN DOOR HANDLE  | 0.00  | 0.00  | CRA *130.00 F   |
| 72  | 1   | NA       | *R/F INN WINDOW MLDG  | 0.00  | 0.00  | de *130.00 F    |
| 73  | 1   | NA       | *R/F WINDOW CHANNEL   | 0.00  | 0.00  | de *150.00 F    |
| 74  | 1   | NA       | *R/F WINDOW REGULATOR | 0.00  | 0.00  | bt *280.00 F    |
| 75  | 1   | NA       | *R/F WIPER ARM        | 0.00  | 0.00  | bt *125.00 F    |
| 76  | 1   | NA       | *R/F WIPER BLADE      | 0.00  | 0.00  | cut *60.00 F    |
| 77  | 1   | NA       | *R/HEADLAMP BRACKET   | 0.00  | 0.00  | X SVC *130.00 F |
| 78  | 1   | NA       | *R/INN DOOR LOCK      | 0.00  | 0.00  | bt *120.00 F    |
| 79  | 1   | NA       | *R/INN IMPACT DAMPER  | 0.00  | 0.00  | bt *540.00 F    |
| 80  | 1   | NA       | *R/INN WHEELHOUSE CVR | 0.00  | 0.00  | X SVC *380.00 F |
| 81  | 1   | NA       | *R/LOWER DOOR HINGE   | 0.00  | 0.00  | bt *80.00 F     |
| 82  | 1   | NA       | *R/LOWER H-LAMP MLDG  | 0.00  | 0.00  | cut *130.00 F   |
| 83  | 1   | NA       | *R/OUTER DOOR HANDLE  | 0.00  | 0.00  | X SVC *130.00 F |
| 84  | 1   | NA       | *R/POSITION LAMP      | 0.00  | 0.00  | CRA *350.00 F   |
| 85  | 1   | NA       | *R/RADIATOR SEAL      | 0.00  | 0.00  | X M *150.00 F   |
| 86  | 1   | NA       | *R/R LOCKING          | 0.00  | 0.00  | JAM *350.00 F   |
| 87  | 1   | NA       | *R/SIDE FRAME         | 0.00  | 0.00  | bt *2,580.00 F  |

Goldbell Engineering Pte Ltd/YN8716X/29/04/2021 15:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

| No. | Qty | Part No. | Particulars           | %Disc | %Depr |       | Amount        |
|-----|-----|----------|-----------------------|-------|-------|-------|---------------|
| 88  | 1   | NA       | *R/SIDE MEMBER        | 0.00  | 0.00  | X SVC | *280.00 F     |
| 89  | 1   | NA       | *R/UPPER DOOR HINGE   | 0.00  | 0.00  | BT    | *80.00 F ✓    |
| 90  | 1   | NA       | *R/WIPER SHAFT        | 0.00  | 0.00  | X SVC | *230.00 F     |
| 91  | 1   | NA       | *RADIATOR             | 0.00  | 0.00  | X SVC | *1,500.00 F   |
| 92  | 1   | NA       | *RADIATOR GRILLE SEAL | 0.00  | 0.00  | X NA  | *150.00 F     |
| 93  | 1   | NA       | *REAR PRESSURE HOSE   | 0.00  | 0.00  | X SVC | *280.00 F     |
| 94  | 1   | NA       | *REAR SCREEN          | 0.00  | 0.00  | BRO   | *450.00 F ✓   |
| 95  | 1   | NA       | *REAR SCREEN SEAL     | 0.00  | 0.00  | X NA  | *- F          |
| 96  | 1   | NA       | *REAR SCREEN SEAL     | 0.00  | 0.00  | ACC   | *50.00 F ✓    |
| 97  | 1   | NA       | *RIGHT FRONT DOOR     | 0.00  | 0.00  | BUC   | *1,250.00 F ✓ |
| 98  | 1   | NA       | *RIGHT HEADLAMP ASSY  | 0.00  | 0.00  | CRA   | *420.00 F ✓   |
| 99  | 1   | NA       | *ROOF                 | 0.00  | 0.00  | X SVC | *1,380.00 F   |
| 100 | 1   | NA       | *UP COWL PANEL GRILLE | 0.00  | 0.00  | MIS   | *80.00 F ✓    |
| 101 | 1   | NA       | *UPPER MOULDING       | 0.00  | 0.00  | X NA  | *- F          |
| 102 | 1   | NA       | *WASHER CONTAINER CPL | 0.00  | 0.00  | X SVC | *140.00 F     |
| 103 | 1   | NA       | *WINDSCREEN           | 0.00  | 0.00  | BRO   | *1,280.00 F ✓ |
| 104 | 1   | NA       | *WINDSCREEN SEAL      | 0.00  | 0.00  | ACC   | *350.00 F ✓   |
| 105 | 1   | NA       | *WIPER MOTOR          | 0.00  | 0.00  | X SVC | *195.00 F     |
| 106 | 1   | NA       | *SUNDRY PARTS         | 0.00  | 0.00  | X NA  | *- F          |

F=Franchise part.

Total Parts (S\$)

55,391.00

Goldbell Engineering Pte Ltd/YN8716X/29/04/2021 15:03. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                   | Lab.Type | Amount   |
|-------------------------|-------------------------------|----------|----------|
| <u>Paintwork Labour</u> |                               |          |          |
| 1                       | Total Paint Labour            | New      | 1,226.00 |
| <u>Labour Items</u>     |                               |          |          |
| 2                       | Total Panel/Mechanical Labour | New      | 4,410.00 |
| Gross Labour Cost (S\$) |                               |          | 5,636.00 |

Goldbell Engineering Pte Ltd/YN8716X/29/04/2021 15:03. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

