



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105370

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/08/2021
Reference CC6/CTI21005310/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 4625E
Insured Veh. GBK 3681H
Claim No. SNM21D202480/C02
Policy No. DMCVSNA00053312000
Accident Date 23/04/2021
Inspection Date 26/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21005310/Aea3q2 Date: 01/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 3681H	Veh. Inspected	SMG 4625E
	Policy No.	DMCVSNA00053312000	Coverage (\$)	0.00
	Claim No.	SNM21D202480/C02	Excess (\$)	0.00
	Assign From		Assign Date	26/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN BEETLE	c.c	1197
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WVWZZZ16ZDM639642	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	TOYO	6 mm
	L/H Front Tyre	225/45 R18	TOYO	6 mm
	R/H Rear Tyre	225/45 R18	TOYO	6 mm
	L/H Rear Tyre	225/45 R18	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/04/2021	Inspection Date	26/04/2021
	Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		24 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 4625E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIR BAG ASSY INSTR/PASSENGER	ACTIVATED	2,050.00	2,050.00
1	AIR BAG ASSY INSTR DRIVER	ACTIVATED	1,950.00	1,950.00
1	AIR BAG MODULE DRIVWR SIDE	ACTIVATED	1,080.00	1,080.00
1	SAFETY BELT FRT RH	ACTIVATED	780.00	780.00
1	SAFETY BELT FRT LH	ACTIVATED	780.00	780.00
1	BONNET	TO REPAIR SEE LABOUR	850.00	-
1	BONNET EMBLEM	NECESSARY	65.00	65.00
1	FRONT BUMPER	DEFORMED	920.00	920.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	290.00	290.00
1	FRONT BUMPER REINFORCEMENT	BENT	260.00	260.00
2	FOG LAMP COVER @\$115.00	NOT NECESSARY	230.00	-
1	RADIATOR	DENTED	880.00	880.00
1	CONDENSER	DENTED	640.00	640.00
1	RADIATOR FAN COWLING	NOT NECESSARY	255.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	145.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	285.00	-
1	SUPPORT ASSY ,HOOD	CRACKED	850.00	850.00
1	FRONT WINDSCREEN	CRACKED	1,350.00	1,350.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	155.00	155.00
2	FOG LAMP @\$205.00	NOT NECESSARY	410.00	-
1	TRUNK LID	DISTORTED	1,305.00	1,305.00
1	REAR TRUNKLID GLASS	SHATTERED	990.00	990.00
1	REAR TRUNKLID WEATHERSTRIP	CUT	195.00	195.00
1	REAR TRUNKLID LOCK	JAMMED	205.00	205.00
1	REAR TRUNKLID TRIM BOARD	NOT NECESSARY	420.00	-
1	REAR FENDER RH	DISTORTED	865.00	865.00
1	REAR FENDER INNER TRIM RH	DEFORMED	480.00	480.00
1	REAR END PANEL	DISTORTED	570.00	570.00
1	REAR INNER PANEL RH	TO REPAIR SEE LABOUR	750.00	-

Report Ref No. CC6/CTI21005310/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL BEARING	NOT NECESSARY	255.00	-
1	REAR FENDER GLASS MOULDING	NECESSARY	185.00	185.00
1	REAR FENDER 1/4 GLASS	SHATTERED	280.00	280.00
1	REAR CHASSIS MEMBER RH	TO REPAIR SEE LABOUR	980.00	-
1	REAR SPARE TYRE PANEL	DISTORTED	860.00	860.00
1	REAR SPARE TYRE BOARD	NOT NECESSARY	420.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	195.00	-
1	REAR AXLE	BENT	2,950.00	2,950.00
	LESS 10% DISCOUNT		-2,613.00	-2,093.50
			23,517.00	18,841.50
	<u>SPECIAL NETT ITEMS</u>			
3	WINDSCREEN GLUM @\$60.00 (SN)	NECESSARY	180.00	120.00
1	REAR TYRE (SN)	NOT NECESSARY	175.00	-
1	REAR TYRE RIM (SN)	NOT NECESSARY	450.00	-
1	SET FRONT NUMBER PLATE & BASE PLATE (SN)	MISSING	50.00	50.00
1	SET REAR NUMBER PLATE & BASE (SN)	DISTORTED	50.00	50.00
			905.00	220.00
	<u>LABOUR</u>			
	KNOCKING ,CUTTINGS JACKING WELDING ETC.INCLUSIVE OF THE REPAIR OF BONNET ,REAR INNER PANEL RH AND REAR CHASSIS MEMBER RH .		2,500.00	2,400.00
	SPRAY PAINTING ON AFFECTED AREA.		2,500.00	1,800.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		120.00	60.00
	TOWING .		80.00	60.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		150.00	120.00
	REMOVE & REFIX FRONT & REAR UNDERCARRIAGE.		180.00	180.00
	REMOVE & REFIX FRONT & REAR WINDSCREEN.		240.00	240.00
			5,770.00	4,860.00
	GRAND TOTAL		30,192.00	23,921.50

Report Ref No. CC6/CTI21005310/Aea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,000.00
---	--	--	------------------

Report Ref No. CC6/CTI21005310/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 4625E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 4625E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 4625E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

