

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deland</i>	1	\$ 682.70	\$ 682.70
2	FRONT BUMPER NUMBER PLATE GARNISH <i>Deland</i>	1	\$ 364.70	\$ 364.70
3	FRONT BUMPER FOG LAMP <i>New</i>	2	\$ 516.10	\$ 1,032.20
4	FRONT BUMPER FOG LAMP COVER CHROME <i>New</i>	2	\$ 78.90	\$ 157.80
5	FRONT BUMPER TOWING COVER <i>New</i>	2	\$ 26.80	\$ 53.60
6	FRONT BUMPER LOWER GRILLE <i>Deland</i>	1	\$ 349.20	\$ 349.20
7	FRONT BUMPER SENSOR <i>New</i>	2	\$ 417.60	\$ 835.20
8	FRONT BUMPER SENSOR RING <i>New</i>	2	\$ 24.10	\$ 48.20
9	FRONT BUMPER SENSOR WIRE HARNESS <i>New</i>	1	\$ 288.70	\$ 288.70
10	FRONT BUMPER SIDE RETAINER <i>New</i>	2	\$ 89.60	\$ 179.20
11	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 466.20	\$ 466.20
12	FRONT BUMPER SPONGE <i>Deland</i>	1	\$ 80.50	\$ 80.50
13	FRONT BUMPER BOTTOM COVER <i>Deland</i>	1	\$ 155.70	\$ 155.70
14	FRONT FENDER COWLING <i>New</i>	2	\$ 234.10	\$ 468.20
15	FRONT GRILLE C/W MOULDING <i>Cracked</i>	1	\$ 977.80	\$ 977.80
16	FRONT GRILLE LOGO <i>Ext</i>	1	\$ 265.10	\$ 265.10
17	FRONT GRILLE TOP RUBBER <i>New</i>	1	\$ 31.80	\$ 31.80
18	FRONT GRILLE SIDE GARNISH <i>LH attached</i>	2	\$ 104.20	\$ 208.40
19	FRONT GIRLLE TOP BEAM <i>Cracked</i>	1	\$ 603.70	\$ 603.70
20	HEADLAMP (LED) <i>Cracked</i>	2	\$ 3,976.80	\$ 7,953.60
21	FRONT BONNET <i>Repis</i>	1	\$ 855.60	\$ 855.60
22	FRONT BONNET MOULDING <i>New</i>	1	\$ 366.80	\$ 366.80
23	FRONT BONNET HINGE <i>New</i>	2	\$ 64.60	\$ 129.20
24	FRONT BONNET STOPPER <i>2nd</i>	2	\$ 28.90	\$ 57.80
25	FRONT BONNET LOCK <i>New</i>	1	\$ 135.80	\$ 135.80
26	FRONT SUPPORT PANEL <i>Repis</i>	1	\$ 1,550.60	\$ 1,550.60
27	FRONT SUPPORT PANEL TOP GARNISH <i>Deland</i>	1	\$ 248.50	\$ 248.50

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV2236R**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 27.04.21
 TIME OF ACCIDENT : 15:55HRS

28	FRONT BRACE PANEL <i>Bent</i>	1	\$ 64.50	\$ 64.50	✓
29	HORN <i>Not in</i>	2	\$ 161.40	\$ 322.80	+
30	AIR CON CONDENSER SIDE GARNISH <i>new</i>	2	\$ 94.80	\$ 189.60	+
31	AIR CON CONDENSER <i>Dented</i>	1	\$ 1,949.80	\$ 1,949.80	1451
32	AIR CON CONDENSER MOUNTING <i>new</i>	4	\$ 28.60	\$ 114.40	+
33	RADIATOR TOP SUPPORT GARNISH <i>Crushed</i>	1	\$ 121.80	\$ 121.80	✓
34	RADIATOR <i>Dented</i>	1	\$ 2,287.10	\$ 2,287.10	1710
35	RADIATOR TOP BRACKET <i>new</i>	2	\$ 94.30	\$ 188.60	+
36	RADIATOR FAN COWLING <i>Not in</i>	1	\$ 339.80	\$ 339.80	+
37	RADIATOR RUBBER MOUNTING <i>new</i>	4	\$ 28.20	\$ 112.80	+
38	FRONT TEMPERATURE SENSOR <i>new</i>	1	\$ 143.80	\$ 143.80	+
39	RELAY ADAPTOR <i>Not in</i>	1	\$ 121.80	\$ 121.80	+
40	RELAY ADAPTOR BRACKET <i>2 new</i>	1	\$ 78.20	\$ 78.20	+
41	WIRE ADAPTOR HOLDER <i>1 new</i>	1	\$ 48.50	\$ 48.50	+
42	RESORNATOR DUCT <i>new</i>	2	\$ 116.67	\$ 233.34	+
43	REAR BUMPER <i>Dented</i>	1	\$ 662.10	\$ 662.10	✓
44	REAR BUMPER TOWING COVER <i>Missing</i>	2	\$ 24.20	\$ 48.40	✓
45	REAR BUMPER REFLECTOR <i>Both crushed</i>	2	\$ 59.80	\$ 119.60	1451
46	REAR BUMPER SIDE INNER GARNISH <i>new</i>	2	\$ 290.70	\$ 581.40	+
47	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 103.40	\$ 206.80	✓
48	REVERSE SENSOR <i>Damaged 2 pieces</i>	4	\$ 417.80	\$ 1,671.20	650
49	REVERSE SENSOR RING HOLDER <i>new</i>	4	\$ 24.10	\$ 96.40	✓
50	REVERSE SENSOR WIRE HARNESS <i>Snapped</i>	1	\$ 288.10	\$ 288.10	✓
51	TAILGATE <i>Distorted</i>	1	\$ 2,040.50	\$ 2,040.50	1956
52	TAILGATE LAMP <i>crushed</i>	2	\$ 687.40	\$ 1,374.80	1294
53	TAILGATE INNER AUTO SWITCH BUTTON <i>new</i>	1	\$ 192.80	\$ 192.80	+
54	TAILGATE OUTER SWITCH BUTTON <i>new</i>	1	\$ 248.20	\$ 248.20	+
55	TAILGATE NUMBER PLATE LAMP <i>Damaged</i>	2	\$ 290.60	\$ 581.20	+
56	TAILGATE REVERSE CAMERA <i>Damaged</i>	1	\$ 986.40	\$ 986.40	780
57	TAILGATE WIRE HARNESS <i>new</i>	1	\$ 342.60	\$ 342.60	+
58	TAIL GATE LOGO <i>new</i>	1	\$ 78.20	\$ 78.20	✓
59	TAIL GATE EMBLEM 'ALPHARD' <i>new</i>	1	\$ 75.60	\$ 75.60	✓
60	TAILGATE LOCK DETECTOR <i>Crushed</i>	1	\$ 194.70	\$ 194.70	✓
61	TAILGATE LOCK DETECTOR WIRE HARNESS <i>new</i>	1	\$ 269.60	\$ 269.60	+
62	TAIL GATE LOCK BUZZER <i>Crushed</i>	1	\$ 148.60	\$ 148.60	✓
63	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 800.70	\$ 800.70	768
64	TAILGATE LOWER LOCK <i>new</i>	1	\$ 55.70	\$ 55.70	+

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLV2236R**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 27.04.21
TIME OF ACCIDENT : 15:55HRS

65	TAILGATE INNER TRIM	1	\$ 734.85	\$ 734.85
66	TAILGATE INNER SIDE TRIM	2	\$ 123.80	\$ 247.60
67	TAILGATE INNER HOLDER	1	\$ 52.10	\$ 52.10
68	TAILGATE WEATHER STRIP	1	\$ 324.72	\$ 324.72
69	TAILGATE STOPPER	4	\$ 25.10	\$ 100.40
70	TAILGATE ABSORBER	2	\$ 351.80	\$ 703.60
71	TAILGATE AUTO SENSOR	2	\$ 877.60	\$ 1,755.20
72	TAILGATE AUTO MOTOR	1	\$ 2,812.70	\$ 2,812.70
73	TAILGATE WINDSCREEN C/W MOULDING	1	\$ 1,297.40	\$ 1,297.40
74	TAILGATE SPOILER	1	\$ 963.70	\$ 963.70
75	REAR AIR CON BLOWER MOTOR	1	\$ 1,869.70	\$ 1,869.70
76	TAILLAMP	2	\$ 689.20	\$ 1,378.40
77	TAILLAMP PANEL (OUTER)	2	\$ 187.20	\$ 374.40
78	TAILLAMP PANEL (INNER)	2	\$ 198.60	\$ 397.20
79	TAILLAMP PANEL (INNER) LOWER	2	\$ 178.90	\$ 357.80
80	REAR CORNER PANEL	2	\$ 290.30	\$ 580.60
81	REAR CORNER PANEL RETAINER	2	\$ 98.20	\$ 196.40
82	REAR FENDER INNER TRIM	2	\$ 2,024.20	\$ 4,048.40
83	REAR FENDER INNER COWLING	2	\$ 236.80	\$ 473.60
84	REAR FENDER QUARTER GLASS LH	1	\$ 465.70	\$ 465.70
85	REAR FENDER QUARTER GLASS MOULDING LH	1	\$ 101.30	\$ 101.30
86	REAR END PANEL (OUTER)	1	\$ 781.70	\$ 781.70
87	REAR END PANEL (INNER)			
88	REAR END PANEL TOP GARNISH	1	\$ 167.90	\$ 167.90
89	REAR END PANEL INNER SUPPORT RH	1	\$ 138.60	\$ 138.60
90	REAR FLOOR PANEL	1	\$ 818.20	\$ 818.20
91	REAR FLOOR PANEL BOTTOM CROSS MEMBER	1	\$ 2,764.10	\$ 2,764.10
92	REAR FLOOR PANEL TOP BOARD (SIDE)	2	\$ 489.10	\$ 978.20
93	REAR FLOOR PANEL TOP BOARD (CENTER)	1	\$ 281.90	\$ 281.90
94	REAR FLOOR SIDE GARNISH	1	\$ 155.70	\$ 155.70
95	REAR FLOOR PANEL TRAY (CENTER)	1	\$ 358.20	\$ 358.20
96	REAR SEAT RAILWAY (CENTER)	2	\$ 1,230.10	\$ 2,460.20
97	REAR SEAT RAILWAY (SIDE)	2	\$ 760.80	\$ 1,521.60
98	REAR SEAT RAILWAY CENTER COVER GARNISH	2	\$ 209.80	\$ 419.60
99	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT	4	\$ 48.20	\$ 192.80
100	REAR SPARE TYRE BOLT	1	\$ 59.80	\$ 59.80
101	REAR SPARE TYRE HOLDER GARNISH	1	\$ 72.10	\$ 72.10

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV2236R**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 27.04.21
 TIME OF ACCIDENT : 15:55HRS

102	REAR EXHAUST PIPE <i>Regis</i>	1	\$ 754.20	\$ 754.20	+
103	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 26.10	\$ 52.20	+

34418.07
25813.55

TOTAL PRICE	\$ 67,140.01
LESS 25%	\$ 16,785.00
SUB TOTAL PRICE	\$ 50,355.01

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	50
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
5	FRONT BONNET SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
6	FRONT BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	FRONT BONNET MOULDING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	+
9	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20
10	FRONT SUPPORT PANEL BOTTOM COVER GARNISH <i>new</i>	1	\$ 60.00	\$ 60.00	+
11	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
12	RADIATOR TOP SUPPORT GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
13	COOLANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
14	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	60
15	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
16	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
17	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
18	TAILGATE INNER SIDE TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
19	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
20	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	40
21	TAIL GATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 650.00	\$ 650.00	250
22	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	20
23	TAILLAMP PANEL (OUTER) SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
24	TAILLAMP PANEL (INNER) SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
25	TAILLAMP PANEL (INNER) LOWER SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
26	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	60
27	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20
28	REAR FENDER QUARTER GLASS SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00	+
29	REAR FENDER QUARTER GLASS INNER SEAL LH <i>new</i>	1	\$ 80.00	\$ 80.00	+
30	REAR FENDER QUARTER GLASS SOLAR FILM LH <i>new</i>	1	\$ 350.00	\$ 350.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV2236R**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 27.04.21
 TIME OF ACCIDENT : 15:55HRS

31	REAR END PANEL (OUTER) SEALANT <i>3/4</i>	1	\$ 150.00	\$ 150.00	<i>40</i>
32	REAR END PANEL (INNER) SEALANT <i>3/4</i>	1	\$ 150.00	\$ 150.00	<i>40</i>
33	REAR END PANEL TOP GARNISH CLIP (SET) <i>1/2</i>	1	\$ 60.00	\$ 60.00	<i>20</i>
34	REAR FLOOR PANEL SEALANT <i>Not in</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
35	REAR SEAT RAILWAY CENTER COVER GARNISH CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
36	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
37	TRIANGLE BREAKDOWN SIGN <i>Not in</i>	1	\$ 180.00	\$ 180.00	<i>+</i>

820 TOTAL \$ 4,480.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600.</i>
3	TURFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>X</i>
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X.</i>
7	REMOVE AND REFIX AND RESET FRONT SENSOR	\$ 80.00	<i>50</i>
8	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
9	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	<i>X 120</i>

1550

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,800.00	<i>1400 1600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000 1300.</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV2236R**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 27.04.21
 TIME OF ACCIDENT : 15:55HRS

3	TUFF COAT	\$ 250.00	100
4	REMOVE AND REPLACE REAR WIREHARNES	\$ 480.00	x.
5	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	180
6	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	60.
7	REMOVE & REFIX REVERSE CAMERA & DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	x.
9	REMOVE AND REFIX REAR AIRCON BLOWER AND REFILL AIRCON GAS	\$ 350.00	x.
10	REAR CHASSIS ALIGNMENT	\$ 250.00	x.
11	REMOVE & REFIX AND RESET TAILGATE AUTO SYSTEM	\$ 450.00	120.
12	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
13	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
14	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
15	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80

TOTAL \$ 12,310.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 54,835.01
 TOTAL LABOUR COST : \$ 12,310.00
 TOTAL REPAIR COST : \$ 67,145.01

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES before/after spray painting

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
 MICHELLE (HP : 9856 4815)

- EKK Auto Consultants hereby notify the Repairer of the following:**
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian Lj
 h/c 29/04/21.

15 days. Supplementary: 510.60

total: 32384.157

2/s: 25.9K.

25.9K

3690

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 29.04.21

TO : **AIG** MOTOR CLAIMS DEPTS (SUPPLEMENTARY)
VEHICLE NO : **SLV2236R**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 27.04.21
TIME OF ACCIDENT : 15:55HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE OUTER MOULDING (CHROME)	1	\$ 680.80	\$ 680.80

cracked.

TOTAL PRICE	\$	680.80
LESS 25%	\$	170.20
SUB TOTAL PRICE	\$	510.60

ESTIMATE REPORT

TOTAL PARTS COST : \$ 510.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE (HP : 9856 4815)