

# AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M



bigSAFE

TO:

China Taiping Insurance (S) Pte Ltd - Claims Dept  
3 Anson Rd,  
#16-00 Springleaf Tower  
Singapore 079909

## Quotation

DATE: 12-May-21

TERMS: 30 Days

PAGE NO.: Page 1 of 1

24207.29  
259  
18155.46

6738.26

| S/N        | DESCRIPTION                                                                       | UOM | QTY | UNIT PRICE | AMOUNT (\$)              |
|------------|-----------------------------------------------------------------------------------|-----|-----|------------|--------------------------|
|            | <b>Own Damage Repair : XE1401J DOA: 21/04/21</b>                                  |     |     |            |                          |
| 42         | Front Fender Bracket - LH <i>su</i>                                               |     | 1   | 232.59     | \$ 232.59 X              |
| 43         | Side Mirror Stay - LH <i>st</i>                                                   |     | 1   | 817.09     | \$ 817.09                |
| 44         | Side Mirror (Big) - LH <i>ms</i>                                                  |     | 1   | 177.68     | \$ 177.68                |
| 45         | Side Mirror (Square) - LH <i>ms</i>                                               |     | 1   | 159.83     | \$ 159.83                |
| 46         | Side Mirror (Small) - LH <i>ms</i>                                                |     | 1   | 107.24     | \$ 107.24                |
| 47         | Side Mirror Stay Top - LH <i>st</i>                                               |     | 1   | 316.31     | \$ 316.31                |
| 48         | Cabin Rear Corner Panel - LH <i>su</i>                                            |     | 1   | 2,154.21   | \$ 2,154.21 X            |
| 49         | Cabin Rear Corner Inner Panel - LH <i>su</i>                                      |     | 1   | 748.51     | \$ 748.51 X              |
| 50         | Cabin Rear Corner Inner Panel Garnish - LH <i>su</i>                              |     | 1   | 287.37     | \$ 287.37 X              |
| 51         | Cabin Rear Corner Side Trim - LH <i>su</i>                                        |     | 1   | 1,312.39   | \$ 1,312.39 X            |
| 52         | Cabin Rear Panel Glass <i>bro</i>                                                 |     | 1   | 1,432.00   | \$ 1,432.00              |
| 53         | Cabin Rear Panel Glass Rubber Seal <i>ne</i>                                      |     | 1   | 230.72     | \$ 230.72                |
| 54         | Aircond Suction Pipe <i>? x su</i>                                                |     | 1   | 338.25     | \$ 338.25 X              |
| 55         | Aircond Discharge Hose <i>? x su</i>                                              |     | 1   | 334.76     | \$ 334.76 X              |
| 56         | Aircond Condensor Assy <i>st</i>                                                  |     | 1   | 3,497.39   | \$ 3,497.39              |
| 57         | Aircond Condensor Fan Motor Assy <i>? x su</i>                                    |     | 1   | 528.17     | \$ 528.17 X              |
| 58         | Aircond Condensor Fan Cowling <i>? x su</i>                                       |     | 1   | 362.01     | \$ 362.01 X              |
| 59         | Aircond Condensor Hose Assy <i>? x su</i>                                         |     | 1   | 199.74     | \$ 199.74 X              |
| 60         | Labour to repair whole cabin, dismantle & renew all parts JOB to spray & painting |     | 1   | \$5,000.00 | \$ 5,000.00              |
| E. & O. E. |                                                                                   |     |     |            | SUB-TOTAL \$41,174.05    |
| SGD:       |                                                                                   |     |     |            | 7% GST \$2,882.18        |
|            |                                                                                   |     |     |            | <b>TOTAL \$44,056.23</b> |

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

AAK LOGISTICS SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rasul*  
Hp 96010068

Authorised Signature

14 days

HS

30/04/21 @ 1600

EXCESS: 3000

Revert

Re-survey after repair

*Peijuan*

18155.46

3500.00

21,655.46

20%

17,324.36

45-17,300