

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK2234Y

MAKE & MODEL : TOYOTA / HIACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P100250309

DATE : 29 Apr 2021

CLAIM TYPE : OD CLAIM

D.O.A : 28 Apr 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	COST PRICE	TOTAL PRICE
1	1	FRONT BUMPER	OR	\$ 170.00	\$ 170.00
2	1	FRONT BUMPER GRILLE	X NN	\$ 60.00	\$ 60.00
3	21	FRONT BUMPER SIDE RETAINER	(LH) - OR	\$ 55.00	\$ 110.00
4	1	FRONT BUMPER REINFORCEMENT	- RT	\$ 65.00	\$ 65.00
5	1	FRONT BUMPER CENTRE BEAM	(LH) - RT	\$ 45.00	\$ 45.00
6	1	FRONT GRILLE TOP	X NN	\$ 90.00	\$ 90.00
7	1	FRONT GRILLE LOWER	- OR	\$ 120.00	\$ 120.00
8	1	FRONT GRILLE INNER	X NN	\$ 170.00	\$ 170.00
9	2	HEADLAMP ASSY LH/RH	OR (LH & RH)	\$ 280.00	\$ 560.00
10	21	HEADLAMP ASSY BRACKET LH/RH	(LH) - OR	\$ 10.00	\$ 20.00
11	1	BONNET	- OR	\$ 200.00	\$ 200.00
12	1	BONNET LOCK	X NN	\$ 35.00	\$ 35.00
13	21	BONNET HINGES	(LH) - OT	\$ 22.00	\$ 44.00
14	1	CORNER PANEL RH	- MIS	\$ 55.00	\$ 55.00
15	1	BRACE PANEL	X NN	\$ 22.00	\$ 22.00
16	1	FRONT SUPPORT PANEL	- OT	\$ 140.00	\$ 140.00
17	1	FIRE WALL PANEL	X RT X - DO	\$ 400.00	\$ 400.00
18	1	FIRE WALL PANEL CROSSMEMBER	- DO	\$ 150.00	\$ 150.00
19	1	FIRE WALL PANEL INSULATOR	- TN	\$ 120.00	\$ 120.00
20	1	DASHBOARD	- CRV	\$ 380.00	\$ 380.00
21	1	DASHBOARD REINFORCEMENT	? X NN	\$ 260.00	\$ 260.00
22	1	DASHBOARD STEERING LOWER COVER RH	? X NN	\$ 160.00	\$ 160.00
23	1	DASHBOARD CENTRE LOWER COVER RH	? X NN	\$ 95.00	\$ 95.00
24	1	PARKING BRAKE HOLE COVER	? X NN	\$ 65.00	\$ 65.00
25	1	DASHBOARD CENTRE CONSOLE	? X NN	\$ 250.00	\$ 250.00
26	1	DASHBOARD CENTRE LOWER COVER LH	? X NN	\$ 120.00	\$ 120.00
27	1	GLOVE BOX	- OR	\$ 130.00	\$ 130.00
28	1	FRONT WINDSCREEN GLASS	- OR	\$ 500.00	\$ 500.00
29	2	FRONT WINDSCREEN GLASS MOULDING	- MR	\$ 35.00	\$ 70.00
30	1	WIPER PANEL GARNISH	- OR	\$ 175.00	\$ 175.00
31	1	WIPER PANEL GARNISH RH (SMALL)	X NAI	\$ 18.00	\$ 18.00
32	1	WIPER MOTOR	? X NN	\$ 280.00	\$ 280.00
33	1	WIPER LINK ASSY	? X NN	\$ 105.00	\$ 105.00
34	1	TOYOTA LOGO	X NN	\$ 28.00	\$ 28.00
35	1	FRONT DOOR LH	X R	\$ 550.00	\$ 550.00
36	1	FRONT DOOR OUTER MOULDING LH	X NN	\$ 40.00	\$ 40.00
37	1	FRONT STEP GARNISH LH	- OR	\$ 55.00	\$ 55.00
38	1	CONDENSER	- DO	\$ 450.00	\$ 450.00
39	1	DISCHARGE HOSE	X NN	\$ 85.00	\$ 85.00
40	1	SUCTION HOSE	X NN	\$ 110.00	\$ 110.00
41	1	LIQUID PIPE	X NN	\$ 120.00	\$ 120.00
42	1	RADIATOR	? X NN	\$ 520.00	\$ 520.00
43	1	RADIATOR FAN MOTOR	? X NN	\$ 330.00	\$ 330.00

44	1	RADIATOR FAN BLADE	?	X	MM		\$	60.00	\$	60.00
45	1	RADIATOR FAN COWLING	?	X	MM		\$	100.00	\$	100.00
46	1	RADIATOR SPARE TANK					\$	140.00	\$	140.00
47	1	INTERCOOLER					\$	440.00	\$	440.00
48	1	INTERCOOLER BRACKET	?	X	MM		\$	30.00	\$	30.00
49	1	INTERCOOLER GARNISH TOP					\$	45.00	\$	45.00
50	1	INTERCOOLER GARNISH BOTTOM		X	MM		\$	45.00	\$	45.00
51	1	WASHER TANK					\$	50.00	\$	50.00
52	1	HEATER/AIRCON UNIT					\$	950.00	\$	1,100.00
53	1	BLOWER ASSY					\$	350.00	\$	350.00
54	1	ABS Pipe 1					\$	230.00	\$	230.00
55	1	ABS Pipe 2					\$	75.00	\$	75.00
56	1	ABS Pipe 3					\$	75.00	\$	75.00
57	1	ABS Pipe 4					\$	75.00	\$	75.00
58	1	INTERCOOLER LOWER HOSE	?	X	MM		\$	85.00	\$	85.00
							\$	9,820.00	\$	10,372.00

TOTAL PRICE	\$	10,372.00
PLUS 10%	\$	1,037.20
SUB TOTAL PRICE	\$	11,409.20

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
61	1	FRONT BUMPER CLIPS SET	/ NR	\$ 30 50.00	\$ 50.00
62	1	FRONT DOOR CO.REG. STICKER	/ NR	\$ 20 30.00	\$ 30.00
63	1	TOWING FEE	/ NR	\$ 60 120.00	\$ 120.00
64	1	WINDSCREEN SEALANT	/ NR	\$ 40 60.00	\$ 60.00
65	1	WINDSCREEN INNER SEAL	/ NR	\$ 40.00	\$ 40.00
66	1	WINDSCREEN IU BRACKET	/ NR	\$ 20.00	\$ 20.00
67	1	RADIATOR COOLANT	/ NR	\$ 20 30.00	\$ 30.00
TOTAL S/NETT				\$ 350.00	\$ 350.00

Labour Charges

68	To cut & weld on support panel. To panel beat and straighten fire wall, frt rh pillar floor board. To remove & refit front bumper, bonnet, headlamp, front grille and other attachments.			\$ 2,500.00	1600
69	To putty & spray painting for front bumper, bonnet, frt grille, frt rh door, fire wall, floor board, support panel, and other affected areas			\$ 2,000.00	800
70	To transfer front door LH components			\$ 80.00	X
71	To remove and refit dashboard			\$ 300.00	200
72	To remove and refit radiator, condenser, a/c blower, heater unit and top up a/c gas.			\$ 200.00	150
73	To remove and refit brake booster, master pump, intercooler and other components.			\$ 200.00	80
74	To remove and refit front windscreen glass.			\$ 150.00	120

TOTAL LABOUR

\$ 5,430.00

Total Cost of Repairs

\$ 17,189.20

(Total parts + Total S/Nett + Total Labour Cost)

Stew CLKK)

OD-AM ML

Excess - ?

L/S, My ML sy

12 dys

3/5/21, 10.00am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: