

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	✓	📄	✓	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS3/AIG21005323/Gqf3		
78 SHENTON WAY #09-16		Date: 30/04/2021		
AIG BUILDING				
SINGAPORE 079120		Code: AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBK 2805A	Veh. Inspected	SGX 5237S	
Policy No.		Coverage (\$)	0.00	
Claim No.	1641133875SG	Excess (\$)	0.00	
Assign From	ERIC TEO WEI HONG	Assign Date	30/04/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/04/2021	Inspection Date	30/04/2021	
Survey held at	JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				