

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|----------------|---------|-----------------------|--|
| | SMRT AUTOMOTI | VE SERVICES PTE LTD | | Ref: | CS/SMR21005324/Buf3e2 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 7705 | | Date: | 31/05/2021 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHF 65L | Veh. Inspected | t | SKX 7869H | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/04/21/2078 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 30/04/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA VEZEL 1.5A | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2015 | |
| | Chassis No. | RU11107305 | Colour | | WHITE | |
| | Odometer | 75910 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | | 5 mm | |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | | 5 mm | |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | | 5 mm | |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | | 5 mm | |
| 4. | . Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 28/04/2021 | Inspection Dat | te | 30/04/2021 | |
| | Survey held at | BIFROST AUTO PTE LTD | - | | | |
| | | 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | | | |
| 5a. | | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | | 4 Worki | ng Days | |
| | - | | | | | |