

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLB8514D
Accident Date : 13-May-2020

No. : 06169

Date : 15-May-2020

Our Ref : 020049 (AIG) / CHAN

PAGE : 1

THE NEIGHBOUR CONTRACT
311B ANCHORVALE LANE
#04-24
Singapore 542311

*Not Authorized
C/Rp 82950/r
Purvey After Repair*

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 TURBO GBE9659R

6 days

1 pc N/s sliding door
1 pc N/s rear fender
1 pc Rear bumper
1 pc N/s rocker panel

R 1,445.78 ✓
R 1,469.50 ✓
R 373.10 X
R 356.20 X

Less 25% : 3,644.58
911.14

2,733.44

To apply undersealing

80.00 *601*

To remove roof lining, front and rear seats, trim board and carpet

100.00 *801*

To putty and spray replaced parts

1,000.00 *6001*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

1,200.00 *8001*

Total : S\$ 5,113.44

Singapore Dollars Five Thousand One Hundred and Thirteen and Cents Forty Four Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: