



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 4425H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	1,189.00	1,189.00
1	FRONT BUMPER	DEFORMED	1,058.00	1,058.00
1	FRONT BUMPER SIDE BRACKET RH	DAMAGED	48.00	48.00
1	FRONT BUMPER LAMP RH	SERVICEABLE	112.50	-
1	FRONT BUMPER FOG LAMP RH	SERVICEABLE	266.80	-
1	FRONT BUMPER FOG LAMP COVER RH	SERVICEABLE	125.00	-
1	HEAD LAMP RH	DEFACED	796.00	796.00
1	HEAD LAMP PANEL RH	TO REPAIR SEE LABOUR	125.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	890.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	698.80	-
	LESS 10% DISCOUNT		-530.91	-309.10
			4,778.19	2,781.90
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	55.00	30.00
			55.00	30.00
LABOUR				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF HEAD LAMP PANEL RH, FRONT SUPPORT PANEL AND FRONT FENDER RH.		810.00	400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		700.00	700.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		50.00	30.00
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY).		22.50	22.50
	SPECIALIST CHARGES - DIGNOSTIC FAULT CODE / RESET.		150.00	80.00
			1,732.50	1,232.50
GRAND TOTAL			6,565.69	4,044.40

Report Ref No. CS3/LPC20009991/Eqf3e2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
---	--	--	-----------------

Report Ref No. CS3/LPC20009991/Eqf3e2-1

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.