


176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Date: 30/04/2021
Claim Type: TP
VRN: GBF9433U



Not within
61 Lms & 6500k
Presumably after Paving
9 days

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tail gate 1367.60	1	\$ 1,997.00	\$ 1,997.00
2	Tail gate hinge 3	3	\$ 68.00	\$ 272.00
3	Tail gate stopper C 29	2	\$ 63.00	\$ 126.00
4	Tail gate stopper bracket C 121.	2	\$ 153.00	\$ 306.00
5	Tail gate lower panel 584.30	1	\$ 958.00	\$ 958.00
6	Tail lamp panel 181.40	2	\$ 383.00	\$ 766.00
7	Tail lamp C 251.30	2	\$ 373.00	\$ 746.00
8	Rear licence plate lamp	2	\$ 77.00	\$ 154.00
9	Side gate	2	\$ 2,216.00	\$ 4,432.00
10	Side gate lock C 178	2	\$ 186.00	\$ 372.00
11	Rear spare tyre carrier	1	\$ 486.00	\$ 486.00
12	Tail gate hinge pin	4	\$ 134.00	\$ 536.00
13	Tail gate lock	2	\$ 276.00	\$ 552.00
14	Tail gate lower member	1	\$ 1,714.00	\$ 1,714.00
15	Tail gate lower member hook	2	\$ 158.00	\$ 316.00
16	Exhaust silencer	1	\$ 782.00	\$ 782.00
17	Exhaust hanger	1	\$ 66.00	\$ 66.00
18	Rear floor panel	1	\$ 1,487.00	\$ 1,487.00
19	Side gate hinge pin	12	\$ 153.00	\$ 1,836.00
20	Rear licence plate base panel	1	\$ 270.00	\$ 270.00
21	Rear step bracket	1	\$ 380.00	\$ 380.00
22	Rear storage box assy n/s	1	\$ 525.00	\$ 525.00
23	Front grille 479.80	1	\$ 668.00	\$ 668.00
24	Front grille "TOYOTA" logo	1	\$ 56.00	\$ 56.00
25	Front bumper 691.20	1	\$ 1,086.00	\$ 1,086.00
26	Front bumper bracket n/s R1	2	\$ 146.00	\$ 292.00
27	Front bumper side retainer n/s P	2	\$ 109.00	\$ 218.00
28	Front door inner trim board o/s	1	\$ 465.00	\$ 465.00
29	Front door inner trim board speaker o/s	1	\$ 288.00	\$ 288.00
30	Wing mirror n/s	1	\$ 178.00	\$ 178.00

Repair Estimate

31	Wing mirror cover n/s	1	\$ 244.00	\$ 244.00	X
32	Headlamp <i>e 726.</i>	2	\$ 994.00	\$ 1,988.00	X
33	Front door n/s	1	\$ 1,934.00	\$ 1,934.00	X
34	Front door hinge n/s	2	\$ 221.00	\$ 442.00	X
35	Front bumper fog lamp n/s	1	\$ 288.00	\$ 288.00	X
36	Quarter panel n/s	1	\$ 256.00	\$ 256.00	X
37	Radiator assy	1	\$ 945.00	\$ 945.00	X
38	Radiator hose	2	\$ 89.00	\$ 178.00	X
39	Radiator fan cowling	1	\$ 129.00	\$ 129.00	X
40	Radiator fan motor	1	\$ 137.00	\$ 137.00	X
41	Front door step garnish n/s	1	\$ 221.00	\$ 221.00	X
42	Front door step panel n/s	1	\$ 342.00	\$ 342.00	X
43	Front door weatherstrip n/s	1	\$ 186.00	\$ 186.00	X
44	Front lower panel	1	\$ 655.00	\$ 655.00	X
45	Front windscreen moulding	1	\$ 198.00	\$ 198.00	X
Subtotal				\$ 30,473.00	
List discount				25.00%	
Total				\$ 22,854.75	

Nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear number plate lamp bulb	2	\$ 10.00	\$ 20.00
2	Cargo canopy structure inner <i>DIY</i>	1	\$ 1,200.00	\$ 1,200.00
3	Cargo canopy structure outer <i>DIY</i>	1	\$ 1,600.00	\$ 1,600.00
4	Cargo canopy structure roller rail n/s	1	\$ 900.00	\$ 900.00
5	Cargo canopy structure roller rail o/s	1	\$ 900.00	\$ 900.00
6	Rear cargo floor aluminium board	1	\$ 1,200.00	\$ 1,200.00
7	Tailgate aluminium board	1	\$ 600.00	\$ 600.00
8	Sidegate aluminium board	2	\$ 800.00	\$ 1,600.00
Subtotal				\$ 8,020.00
Nett discount				10.00%
Total				\$ 7,218.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear number plate	1	\$ 55.00	\$ 55.00
2	Tail gate company sticker	1	\$ 300.00	\$ 300.00
3	Rear tailgate "70km/h" sticker	1	\$ 15.00	\$ 15.00
4	Rear tailgate "DYNA" sticker	1	\$ 15.00	\$ 15.00
5	Spare tyre	2	\$ 380.00	\$ 760.00
6	Reverse sensor	1	\$ 280.00	\$ 280.00
7	Sundries	1	\$ 50.00	\$ 50.00
8	Rear tailgate "13 PAX" sticker	1	\$ 15.00	\$ 15.00
9	Rear tailgate "1500KG" sticker	1	\$ 15.00	\$ 15.00
10	Front grille clips	8	\$ 5.50	\$ 44.00
11	Quarter panel n/s clips	6	\$ 5.50	\$ 33.00

Repair Estimate

12	Front bumper rivets	nn	10	\$ 5.50	\$ 55.00	X
13	Front door step garnish n/s clips	nn	6	\$ 5.50	\$ 33.00	X
14	Front door inner trim board n/s clips	nn	8	\$ 5.50	\$ 44.00	X
15	Front windscreen sealant	nn	1	\$ 120.00	\$ 120.00	X
16	Radiator coolant	nn	1	\$ 80.00	\$ 80.00	X
17	Front door company sticker n/s	nn	1	\$ 25.00	\$ 25.00	X
18	Front lower panel sealant	nn	1	\$ 100.00	\$ 100.00	X
19	Front lower panel "DYNA" sticker	nn	1	\$ 35.00	\$ 35.00	X
				Total	\$ 2,074.00	

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	10	\$ 2,000.00	1200h
2	To disconnect front & rear wire harness of electrical components to facilitate repairs, reconnect and check functions including headlamp/taillamp lightings.	0.5	\$ 100.00	40h
3	To remove and replace, straighten and readjust exhaust pipe.	0.5	\$ nn 100.00	X
4	To align rear cargo frame and to conduct chassis alignment on Car-O-Liner.	2	\$ nn 400.00	X
5	Supply spray paint material and necessary items to respray all affected area / panel.	10	\$ 2,000.00	1000h
6	To rust proof all affected portions after repair.	1	\$ 200.00	90h
Total labour			\$ 4,800.00	

Estimate Grand Total	\$ 36,946.75
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: