

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 10 May 2021

Preliminary Advice

Insured Vehicle No	: SGN8082D		
TP Vehicle No	: SLC2025H	Accident Date	: 28/04/2021
Make	: HONDA VEZEL	Assignment Date	: 04/05/2021
Date of Inspection	: 03/05/2021	Est. Duration of Repair	: 5
Inspection At	: CHEONG CHEONG MOTOR SERVICE (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535 SINGAPORE 569535		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,881.68
Revised Amount	:S\$	3,025.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,025.52

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :