

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019625G

**SHCS186D**

AAD2104-134

*Not Authorised**Pehmy Bypoint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

**30 APR 2021****SHCS186D**

JTDKG3FU003092241

TOYOTA

PRIUS GEN 4

27/04/2021

LONPAC

16/10/2020

|   | PART                                       |    | LIST                    |   |
|---|--------------------------------------------|----|-------------------------|---|
| 1 | COVER, REAR BUMPER                         | \$ | B <sub>2</sub> 485.60   | — |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER        | \$ | B <sub>2</sub> 332.70   | — |
| 1 | GUARD, REAR BUMPER, CENTER                 | \$ | B <sub>2</sub> 374.50   | — |
| 1 | COVER, REAR BUMPER, LOWER                  | \$ | B <sub>2</sub> 22.00    | ✓ |
| 1 | RETAINER, REAR BUMPER SIDE, LH             | \$ | B <sub>2</sub> 132.60   | X |
| 1 | RETAINER, REAR BUMPER SIDE, RH             | \$ | B <sub>2</sub> 132.60   | X |
| 1 | REFLECTOR ASSY, REFLEX, LH                 | \$ | B <sub>2</sub> 39.00    | X |
| 1 | REFLECTOR ASSY, REFLEX, RH                 | \$ | B <sub>2</sub> 39.00    | X |
| 1 | BOX, DECK FLOOR, LH                        | \$ | B <sub>2</sub> 313.00   | X |
| 1 | BOX, DECK FLOOR, REAR                      | \$ | B <sub>2</sub> 105.80   | X |
| 1 | BOX, DECK FLOOR, RH                        | \$ | B <sub>2</sub> 313.60   | X |
| 1 | BOARD, REAR FLOOR, NO.1                    | \$ | B <sub>2</sub> 519.00   | X |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK            | \$ | B <sub>2</sub> 651.00   | ? |
| 1 | COVER, DECK TRIM, REAR                     | \$ | B <sub>2</sub> 126.70   | X |
| 1 | COVER, FLOOR UNDER, NO.2 (RH)              | \$ | B <sub>2</sub> 241.90   | X |
| 1 | COVER, FLOOR UNDER, NO.1 (LH)              | \$ | B <sub>2</sub> 175.10   | X |
| 1 | COVER, REAR FLOOR (CTR)                    | \$ | B <sub>2</sub> 229.90   | ✓ |
| 1 | PANEL SUB-ASSY, BACK DOOR                  | \$ | B <sub>2</sub> 1,147.80 | X |
| 1 | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE       | \$ | B <sub>2</sub> 913.60   | ✓ |
| 1 | STAY ASSY, BACK DOOR, LH                   | \$ | B <sub>2</sub> 242.50   | X |
| 1 | STAY ASSY, BACK DOOR, RH                   | \$ | B <sub>2</sub> 242.50   | X |
| 1 | HINGE ASSY, BACK DOOR, LH                  | \$ | B <sub>2</sub> 61.00    | X |
| 1 | HINGE ASSY, BACK DOOR, RH                  | \$ | B <sub>2</sub> 61.00    | X |
| 1 | ORNAMENT SUB-ASSY, BACK DOOR               | \$ | B <sub>2</sub> 47.90    | — |
| 1 | PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2 | \$ | B <sub>2</sub> 54.60    | — |
| 1 | PLATE, BACK DOOR NAME, NO.1                | \$ | B <sub>2</sub> 54.60    | ✓ |

**Trans-cab Auto Services Pte Ltd****AAD2104-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5186D**

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>7,059.50</b> |
| <b>25%</b>   | <b>\$</b> | <b>1,764.88</b> |
|              | <b>\$</b> | <b>5,294.63</b> |

**Special Nett**

|                                |           |                 |       |
|--------------------------------|-----------|-----------------|-------|
| 1SET PARKING AID               | \$        | 700.00          | 2201n |
| 1SET REAR BUMPER CLIP          | \$        | 85.00           | 501n  |
| 1 BUMPER CENTRE GUARD CLIP     | \$        | 80.00           | X     |
| 1 REAR BUMPER PROTECTOR        | \$        | 180.00          | 301n  |
| 1 REAR BUMPER RETAINER CLIP    | \$        | 75.00           | X     |
| 1 BOOT STICKER TRANSCAB        | \$        | 100.00          | 301n  |
| 1 BOOT STICKER 65553333        | \$        | 100.00          | 301n  |
| 2 WINDSCREEN SEALANT           | \$        | 150.00          | 801n  |
| 1 WINDSCREEN MOULDING          | \$        | 200.00          | —     |
| 1 WINDSCREEN INNER SPONGE SEAL | \$        | 130.00          | 301n  |
| <b>TOTAL</b>                   | <b>\$</b> | <b>1,120.00</b> |       |

**TOTAL PARTS \$ 6,414.63****LABOUR**

|                                                                                                                           |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|------|
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$ | 240.00   | ?    |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00   | 601  |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 1,600.00 | 5001 |
| To transfer of rear end panel fittings, attachment to facilitate bodywork repair.                                         | \$ | 380.00   | X    |

**Trans-cab Auto Services Pte Ltd****AAD2104-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5186D**

|                                                                                       |    |          |      |
|---------------------------------------------------------------------------------------|----|----------|------|
| Putty And Spray Painting Of The Affected Portion.                                     | \$ | 1,600.00 | 8601 |
| To Remove And Refit Rear Big & Small W/Screen Glass<br>To Facilitate Bodywork Repair. | \$ | 300.00   | 1801 |
| To reinstall rear bumper parking sensor.                                              | \$ | 170.00   | 501  |
| To Check Electrical Lighting Concerned.                                               | \$ | 170.00   | 201  |

**TOTAL \$ 4,840.00****Over All Total \$ 11,254.63****(PART-BY-PART) Repair Days****10 Days****4 days****LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: