

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019625G

SHCS186D

AAD2104-134

*Not Authorised**Pehmy Bypoint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 APR 2021**SHCS186D**

JTDKG3FU003092241

TOYOTA

PRIUS GEN 4

27/04/2021

LONPAC

16/10/2020

	PART		LIST	
1	COVER, REAR BUMPER	\$	B ₂ 485.60	—
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	B ₂ 332.70	—
1	GUARD, REAR BUMPER, CENTER	\$	B ₂ 374.50	—
1	COVER, REAR BUMPER, LOWER	\$	B ₂ 22.00	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	B ₂ 132.60	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	B ₂ 132.60	X
1	REFLECTOR ASSY, REFLEX, LH	\$	B ₂ 39.00	X
1	REFLECTOR ASSY, REFLEX, RH	\$	B ₂ 39.00	X
1	BOX, DECK FLOOR, LH	\$	B ₂ 313.00	X
1	BOX, DECK FLOOR, REAR	\$	B ₂ 105.80	X
1	BOX, DECK FLOOR, RH	\$	B ₂ 313.60	X
1	BOARD, REAR FLOOR, NO.1	\$	B ₂ 519.00	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	B ₂ 651.00	X
1	COVER, DECK TRIM, REAR	\$	B ₂ 126.70	X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	B ₂ 241.90	X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	B ₂ 175.10	X
1	COVER, REAR FLOOR (CTR)	\$	B ₂ 229.90	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	B ₂ 1,147.80	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	B ₂ 913.60	✓
1	STAY ASSY, BACK DOOR, LH	\$	B ₂ 242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	B ₂ 242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	B ₂ 61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	B ₂ 61.00	X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	B ₂ 47.90	—
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	B ₂ 54.60	—
1	PLATE, BACK DOOR NAME, NO.1	\$	B ₂ 54.60	✓

Trans-cab Auto Services Pte Ltd**AAD2104-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5186D

TOTAL	\$	7,059.50
25%	\$	1,764.88
	\$	5,294.63

Special Nett

1SET PARKING AID	\$	700.00	2201n
1SET REAR BUMPER CLIP	\$	85.00	501n
1 BUMPER CENTRE GUARD CLIP	\$	80.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	301n
1 REAR BUMPER RETAINER CLIP	\$	75.00	X
1 BOOT STICKER TRANSCAB	\$	100.00	301n
1 BOOT STICKER 65553333	\$	100.00	301n
2 WINDSCREEN SEALANT	\$	150.00	801n
1 WINDSCREEN MOULDING	\$	200.00	—
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	301n
TOTAL	\$	1,120.00	

TOTAL PARTS \$ 6,414.63**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	X nn
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	5001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	X nn

Trans-cab Auto Services Pte Ltd**AAD2104-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5186D

Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	8601
To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	1801
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 4,840.00**Over All Total \$ 11,254.63****(PART-BY-PART) Repair Days****10 Days****4 days****LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: