

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21005336/EQF3E2

Date: 18/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070056739
Claimant Vehicle No : FBQ9455Z **Insured Vehicle No :** SMT504D
Date of Loss: 29/04/2021 Nature of Claim: TP Claim No: 8736734813SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ9455Z**
Make & Model: HONDA ADV150, 149cc ABS CVT Engine No: KF61E1007840
Reg. Date: 09/01/2020 (Man. Year: 2020) Chassis No: MH1KF6110KK007856
Colour: Red Odometer: 21226 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 130/70-13
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/04/2021
Date Inspected: 03/05/2021 Inspected At: TWO-WHEELED AFFAIR (HQ)
39 Woodlands Close, Mega@Woodlands #03-04,
Singapore 737856
Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

MARKET VALUE: \$12,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$3,137.00 =NETT VALUE:
\$9,363.00

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >