

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: GBC7920J210421

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 28-04-21

Address Motor Claims Department

Vehicle No: GBC7920J

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Sliding Door <i>DD / Bent 1455.10</i>	\$ 1,452.10	<i>X</i> <i>500 S.N</i>
2	Fender <i>R</i>	\$ 1,468.10	
3	"Corporate" Advertisement & Artwork <i>new</i>	\$ 800.00	
	To check all wiring & electrical component for proper function	\$ 30.00	<i>11X</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	<i>250</i>
	To putty & spray painting & including touch up paint on accident affected areas	\$ 700.00	<i>450</i>
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	<i>30</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 5,100.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Bro Auto Engrg Wks

N. f. Anthony

Alan

30/4/21

2/5 \$ 1800 / 4 days.

** Hk Cecilia*

Liu's Auto Consultants notice notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: