



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202145

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 13/04/2022
Reference CC4/LPC21005343/Aga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJL 5232H
Insured Veh. YM 8927J
Claim No. 20/21/21/VC05/024476
Policy No. Z/20/VC05/004193-001
Accident Date 16/04/2021
Inspection Date 08/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21005343/Aga3q2 Date: 13/04/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 8927J	Veh. Inspected	SJL 5232H	
Policy No.	Z/20/VC05/004193-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024476	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	30/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDD2040412A202753	Colour	GREY	
Odometer	130574 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	PIRELLI	6 mm	
L/H Front Tyre	235/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/04/2021	Inspection Date	08/07/2021	
Survey held at	EXCLUSIVE ENTERPRISE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 5232H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR	DENTED	1,568.30	1,568.30
1	REAR DOOR CHROME GARNISH RH	NECESSARY	185.20	185.20
1	REAR DOOR LOCK	NOT NECESSARY	452.20	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,256.30	-
1	REAR FENDER UNDERCOWLING RH	NOT NECESSARY	266.40	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	608.20	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	996.20	-
1	REAR KNUCKLE ARM BEARING RH	NOT NECESSARY	230.00	-
1	REAR LOWER ARM RH	NOT NECESSARY	366.00	-
1	REAR TRAILING ARM RH	NOT NECESSARY	386.20	-
	LESS 10% DISCOUNT		-631.50	-175.35
			5,683.50	1,578.15
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR BLACK TAPE (SN)	NECESSARY	100.00	60.00
1	REAR DOOR INNER TRIMBOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER UNDERCOWLING CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR RIM RH (SN)	CUT	1,000.00	600.00
1	REAR TYRE RH (SN)	NOT NECESSARY	600.00	-
			1,800.00	660.00
	<u>LABOUR</u>			
	WIRE CHECK.		50.00	30.00
	TRANSFER REAR DOOR RH COMPONENT FROM OLD TO NEW .		100.00	80.00
	R/R REAR SEATS ,CUSHION & CARPET TO FACILITATE REPAIRS.		100.00	40.00
	R/R REAR UNDERCARRIAGE RH .	NOT NECESSARY	250.00	-
	WHEEL ALIGNMENT.		150.00	80.00
	TUFF COAT.		200.00	60.00
	LABOUR .INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,200.00	400.00

Report Ref No. CC4/LPC21005343/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINTING.		1,200.00	400.00
			3,250.00	1,090.00
GRAND TOTAL			10,733.50	3,328.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC4/LPC21005343/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 5232H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 5232H

RE-INSPECTION

