

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21005344/BTEQ2
Date: 08/06/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001420285
Claimant Vehicle No :	YN2424C	Insured Vehicle No :	SKT4614S
Date of Loss:	29/04/2021	Nature of Claim:	TP
		Claim No:	256753

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN2424C	Engine No:	4M42A88206
Make & Model:	MITSUBISHI FE83BE6SRDEA, 3.0 D (A)	Chassis No:	FE83BEA20678
Reg. Date:	13/09/2011 (Man. Year: 2011)	Odometer:	349759 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205 R16	Rear Tyre Size:	205 R16
Front Left Side:	Casumina 4 mm	Rear Left Side:	Casumina 4 mm
Front Right Side:	Casumina 4 mm	Rear Right Side:	Casumina 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,784.00	2,715.75	17,068.25	86.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,440.00	1,670.00	53.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,894.00	4,155.75	18,738.25	81.85
Approved Total (Overridden) (S\$)		3,300.00		

(S\$)	22,894.00	3,300.00	19,594.00	85.59
+ GST 7.00/7.00% (S\$)	1,602.58	231.00	1,371.58	85.59
Nett Amount (S\$)	24,496.58	3,531.00	20,965.58	85.59

INSPECTION

Date of Assignment: 30/04/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2021)		
Parts:	N/A	MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for YN2424C)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR REFRIGERATOR LH DOOR ASSY	Broken	2,200.00 F	*1,200.00 FL
2	1		*REAR REFRIGERATOR DOOR OUTER HANDLE	Bent	300.00 F	*100.00 FL
3	1		*REAR REFRIGERATOR DOOR OPEN /CLOSE BAR	Not Damaged	450.00 F	*- FL
4	1		*REAR REFRIGERATOR DOOR OPEN /CLOSE BAR LOWER BRACKET	Not Damaged	150.00 F	*- FL
5	1		*REAR REFRIGERATOR DOOR OPEN /CLOSE BAR LOWER CATCH	Not Damaged	120.00 F	*- FL
6	1		*REAR REFRIGERATOR LH DOOR RUBBER SEAL	Not Damaged	380.00 F	*- FL
7	1		*REAR REFRIGERATOR RH DOOR ASSY	Not Damaged	2,200.00 F	*- FL
8	1		*REAR REFRIGERATOR RH DOOR OUTER HANDLE	Not Damaged	300.00 F	*- FL
9	1		*REAR REFRIGERATOR RH DOOR OPEN /CLOSE BAR	Not Damaged	450.00 F	*- FL
10	1		*REAR REFRIGERATOR RH DOOR OPEN /CLOSE BAR LOWER BRACKET	Not Damaged	150.00 F	*- FL
11	1		*REAR REFRIGERATOR RH DOOR OPEN /CLOSE BAR LOWER CATCH	Not Damaged	120.00 F	*- FL
12	1		*REAR REFRIGERATOR RH DOOR RUBBER SEAL	Not Damaged	380.00 F	*- FL
13	1		*REAR REFRIGERATOR DOOR 60KM/H STICKER	Necessary	24.00 F	*20.00 FL
14	1		*REAR REFRIGERATOR DOORS ALUMINIUM SURROUNDING FRAME	Not Damaged	3,800.00 F	*- FL
15	1		*REAR REFRIGERATOR DOORS ALUMINIUM SURROUNDING FRAME RH RUBBER STOPPERS	Not Damaged	80.00 F	*- FL
16	1		*REAR REFRIGERATOR DOORS ALUMINIUM SURROUNDING FRAME LH RUBBER STOPPERS	Not Damaged	80.00 F	*- FL
17	1		*REAR CHASSIS FRAME RH WOODEN MEMBER	Not Damaged	1,300.00 F	*- FL
18	1		*REAR CHASSIS FRAME RH WOODEN MEMBER RUBBER STOPPER	Not Damaged	80.00 F	*- FL
19	4		*REAR CHASSIS FRAME RH WOODEN MEMBER U-BOLTS	Not Damaged	240.00 F	*- FL
20	1		*REAR CHASSIS FRAME LH WOODEN MEMBER	Not Damaged	1,300.00 F	*- FL
21	1		*REAR CHASSIS FRAME LH WOODEN MEMBER RUBBER STOPPER	Not Damaged	80.00 F	*- FL
22	4		*REAR CHASSIS FRAME LH WOODEN MEMBER U-BOLTS	Not Damaged	240.00 F	*- FL
23	1		*REAR CHASSIS FRAME CENTRE BRACKET	Bent	880.00 F	*212.00 FL
24	1		*REAR CHASSIS FRAME CENTRE BRACKET NUMBER PLATE LAMP	Not Damaged	110.00 F	*- FL
25	1		*REAR NUMBER PLATE	Bent	60.00 F	*25.00 FL
26	1		*REAR UNDER-RUN BUMPER	Bent	1,500.00 F	*650.00 FL
27	1		*REAR UNDER-RUN BUMPER RH BRACKET	Bent	480.00 F	*110.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR UNDER-RUN BUMPER LH BRACKET	Bent	480.00 F	*110.00 FL
29	1		*RH TAILLAMP ASSY	Cracked	550.00 F	*132.75 FL
30	1		*LH TAILLAMP ASSY	Cracked	550.00 F	*132.75 FL
31	1		*EXHAUST PIPE	Bent	750.00 F	*325.00 FL
						F=Franchise part. L=ListItemDisc.
				Sub Total (\$)	19,784.00	3,017.50
				- List Item Discount on L Items 0.00/10.00% (\$)	0.00	301.75
				Total Parts (\$)	19,784.00	2,715.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,CHECK REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT /WELD AND RE-ALIGN ALL AFFECTED PANELS	New	2,200.00	1,000.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	500.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	100.00	0.00
5	REMOVE AND REINSTALL EXHAUST PIPE	New	80.00	40.00
6	APPLY PANELS SEALANT ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (S\$)			3,110.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >