



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106897

INV Date 05/10/2021

Reference CC4/LPC21005345/R1gs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLW 2033D

Insured Veh. YM 8741C

Claim No. 20/21/21/VC05/024509

Policy No. Z20VC05005657

Accident Date 27/04/2021

Inspection Date 30/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21005345/R1gs3q2 Date: 05/10/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 8741C	Veh. Inspected	SLW 2033D	
Policy No.	Z20VC05005657	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024509	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	30/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JM6CR10F290310210	Colour	GREY	
Odometer	122745 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R17	FIRENZA	6 mm	
L/H Front Tyre	225/45Z R17	FIRENZA	6 mm	
R/H Rear Tyre	225/45Z R17	FIRENZA	6 mm	
L/H Rear Tyre	225/45Z R17	FIRENZA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	27/04/2021	Inspection Date	30/04/2021	
Survey held at	15 FAN YONG ROAD			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 2033D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP ASSY LH	CRACKED	1,414.00	1,414.00
1	FRONT FENDER LH	BUCKLED	458.00	458.00
1	FRONT FENDER LAMP LH	SERVICEABLE	46.00	-
1	FRONT FENDER COWLING LH	DEFORMED	166.00	166.00
10	FRONT FENDER COWLING CLIPS @\$4.80	NECESSARY	48.00	48.00
1	FRONT DOOR LH	TORN	1,029.00	1,029.00
1	FRONT DOOR STICKER LH	NECESSARY	158.00	158.00
1	FRONT DOOR PROTECTOR LH	NECESSARY	56.00	56.00
	LESS 20% DISCOUNT		-675.00	-665.80
			2,700.00	2,663.20
	<u>LABOUR</u>			
	TO KNOCK AND STRAIGHTEN FRONT DOOR PILLAR LH ,REMOVE & REPLACE ACCIDENT DAMAGED PARTS ,REALIGN ALL CONNECTION .		500.00	400.00
	SPRAY PAINT FRONT FENDER LH ,FRONT DOOR PILLAR LH ,FRONT DOOR LH ,FRONT DOOR PROTECTOR LH .		600.00	600.00
	REMOVE & RELACE FRONT DOOR TRIM BOARD ,MECHANISM & CHECK LOCKING SYSTEM.		60.00	40.00
	RUST PROOF AFFECTED AREAS .		60.00	60.00
			1,220.00	1,100.00
	GRAND TOTAL		3,920.00	3,763.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CC4/LPC21005345/R1gs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 2033D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLW 2033D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

