

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Vehicle Number : SMM6200C
Vehicle Model : HONDA SHUTTLE
Accident Date : 24.04.2021
Original Reg Date : 05.07.2019

Date : 29.04.2021
Chassis : GK82001857
TP Ins. : LONPAC

Carlin

ESTIMATE

1	1 pc	FRONT DOOR RH <i>Repair</i>		1,785.90	<i>+</i>
2	1 pc	FRONT DOOR HANDLE RH <i>xcen</i>		198.80	<i>+</i>
3	1 pc	FRONT DOOR SIDE MIRROR ASSY RH <i>3MP</i>		546.20	<i>+</i>
4	1 pc	FRONT FENDER INNER COWLING RH <i>xcen</i>		189.30	<i>+</i>
5	1 pc	FRONT FENDER RH <i>xcen</i>		645.20	<i>+</i>
6	1 pc	REAR DOOR RH <i>Dented</i>		1,798.20	<i>98%</i>
7	1 pc	REAR DOOR INNERTRIM RH <i>xcen</i>		523.30	<i>+</i>
8	1 pc	REAR DOOR LOWER RUBBER <i>3x4</i>		145.70	<i>+</i>
9	1 pc	REAR DOOR WEATHERSTRIP RH <i>xcen</i>		198.20	<i>+</i>
10	1 pc	REAR DOOR TOP SEAL RH <i>xcen</i>		146.70	<i>+</i>
11	1 pc	REAR DOOR INNER COWLING RH <i>xcen</i>		189.70	<i>+</i>
12	1 pc	REAR FENDER RH <i>xcen</i>		1,654.80	<i>+</i>
13	1 pc	SIDE ROCKER PANEL RH <i>Repair</i>		782.10	<i>+</i>

8,804.10

Less 20% 1,760.82

total 7,043.28

1509.30

1207.44

Special Nett

1	1 pc	SIDE SKIRT (ACCESSORIES) <i>cont del</i>		750.00	600
2	1 SET	FRONT DOOR INNER COWLING CLIPS <i>for</i>		30.00	+
3	1 SET	FRONT DOOR INNER TRIM CLIPS <i>for</i>		30.00	+
4	1 SET	REAR DOOR INNER TRIM CLIPS <i>for</i>		30.00	+
5	1 SET	REAR DOOR INNER COWLING CLIPS <i>for</i>		30.00	+

630.

Labour charge

Panel Beating		1,200.00	500
Spray painting		1,200.00	600
Anti rust		120.00	50
To transfer front door mechanism		150.00	+
To transfer rear door mechanism		150.00	80
Silicon sealant for sideskirt installation		80.00	50
TOTAL		\$ 10,813.28	

1280

Adrian King.
 1/s 30/04/21.
 04 Days.

Total: 3117.44
 1/s: 2 SK.
 ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: