

KUAN QUEK MOTOR

BLK 3 PIONEER ROAD NORTH #01-16 SINGAPORE 628457

TEL : 6264 2189 FAX : 6268 2109

BUSINESS REG. NO. 25455700K

ESTIMATE

INDIA INTERNATIONAL INSURANCE PTE LTD
64, CECIL STREET
#04/#05/#06-02, IOB BUILDING
SINGAPORE 049711

DATE : 30/04/2021
ACCIDENT DATE : 26/04/2021
TYPE OF CLAIM : THIRD PARTY
YOUR INSURED : SLQ8155C

ATTN : MOTOR CLAIMS DEPARTMENT

RE : VEHICLE NO. GBH1408K KIA K2500 LORRY

TO SUPPLY :


REAR TAIL LAMP ASSY RH / BR	1 PC	\$ 176.86
REAR NUMBER PLATE LAMP BH / B CUT	1 PC	\$ 26.00
REAR TAIL GATE FRAME / OO	1 PC	\$ 537.00
REAR TAIL GATE KIA MOTOR STICKER / MC	1 PC	\$ 29.60
REAR NUMBER PLATE AND RIM / OR	1 SET	\$ 50.00
REAR SENSOR / CUT	1 SET	\$ 220.00 N

LABOUR CHARGES :

TO REPLACE REAR SENSOR AND CHECK WIRING	30	\$ 120.00 N
TO RENEW REAR BUMPER GUARD	400	\$ 450.00 N
TO PANEL BEATING, WELDING AND REPAIRING THE DAMAGED PARTS.	400	\$ 600.00
TO REMOVE AND CHANGE THE ABOVE PARTS.	400	\$ 650.00
TO SPRAY PAINTING ON AFFECTED AREAS.		

TOTAL : \$ 2,859.46

S/DOLLARS : TWO THOUSAND EIGHT HUNDRED FIFTY NINE AND CENTS FORTY SIX ONLY.


KUAN QUEK MOTOR

Steve (LKK) 10/5/21, 1.45pm
8322 8813
5 dys
L/S

My AC Shy
ml PrL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date: