

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2104-093

DATE : 30-Apr-2021

POLICY NO. : FWD PNPV2019-00011461-01

VEHICLE REG. NO. : SMD30055

VEHICLE MAKE : HONDA HRV 1.5 DX CVT

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de</i> ✓	1	\$ 880.00	\$ 880.00
2	Rear Bumper Clip <i>re</i> ✓	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>X</i> SVC	1	\$ 30.00	\$ 30.00
4	Rear Bumper Retainer LH <i>+</i> SVC	1	\$ 30.00	\$ 30.00
5	Rear Bumper Reflector RH <i>+</i> SVC	1	\$ 150.00	\$ 150.00
6	Rear Undercover Cover <i>de</i> ✓	1	\$ 280.00	\$ 280.00
7	Rear Tailgate Door <i>bu</i> ✓	1	\$ 1,080.00	\$ 1,080.00
8	Rear Tailgate Door Lock <i>X</i> SVC	1	\$ 280.00	\$ 280.00
9	Rear Tailgate Door Rubber Seal <i>re</i> ✓	1	\$ 120.00	\$ 120.00
10	Rear HRV Emblem <i>re</i> ✓	1	\$ 80.00	\$ 80.00
11	Rear Honda Emblem <i>re</i> ✓	1	\$ 80.00	\$ 80.00
12	Rear i-Vtec Emblem <i>re</i> ✓	1	\$ 80.00	\$ 80.00
13	Rear Spare Tire Board Cover <i>X</i> SVC	1	\$ 350.00	\$ 350.00
14	Rear Tools Sponge Box/Tray <i>re</i> ✓	1	\$ 250.00	\$ 250.00
15	Rear / End Panel Garnish <i>de</i> ✓	1	\$ 200.00	\$ 200.00
16	Rear End Panel <i>bt</i> ✓	1	\$ 480.00	\$ 480.00
17	Rear Floor Panel <i>bu</i> ✓	1	\$ 800.00	\$ 800.00
18	Rear Windscreen Molding <i>re</i> ✓	1	\$ 100.00	\$ 100.00
19	Rear Buzzer <i>re</i> ✓	1	\$ 110.00	\$ 110.00
20	Rear Exhaust <i>+</i> SVC	1	\$ 560.00	\$ 560.00
21	Rear Exhaust Rubber Mount <i>X</i> SVC	2	\$ 40.00	\$ 80.00
Total Spare Parts				\$ 6,070.00
SPECIAL NETT				
22	Rear Windscreen Sealant <i>re</i> ✓	1	\$ 40.00	\$ 40.00
23	Reverse Sensor <i>re</i> ✓	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
LABOUR				
24	Spray Painting Whole Rear include Blending	1	\$ 1,000.00	\$ 800 1,000.00
25	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 800 1,000.00
26	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 60 80.00
27	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ X 80.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2104-093

DATE : 30-Apr-2021

POLICY NO. : FWD PNPV2019-00011461-01

VEHICLE REG. NO. : SMD30055

VEHICLE MAKE : HONDA HRV 1.5 DX CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul
Hp 90010068
04/05/2021 @ 1130
9 days
45
Resurvey after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 60 80.00
29	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
30	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 80 100.00
31	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ X 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Total Labour \$ 2,490.00

Amount Before Excess \$ 8,800.00

Add GST @ 7% 616.00

Total Amount Payable \$ 9,416.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Supplementary
Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2104-093 (SUP)
DATE : 6-May-2021
POLICY NO. : FWD PNPV2019-00011461-01
VEHICLE REG. NO. : SMD30055
VEHICLE MAKE : HONDA HRV 1.5 DX CVTTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Fender Arc LH <i>cm</i> <i>240</i> <i>209</i>	1	\$ 240.00	\$ 240.00
	<i>192</i>			
Total Spare Parts				\$ 240.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
Total Labour				\$ -
Amount Before Excess				\$ 240.00
Add GST @ 7%				16.80
Total Amount Payable				\$ 256.80

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.