

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2104-093

DATE : 30-Apr-2021

POLICY NO. : FWD PNPV2019-00011461-01

VEHICLE REG. NO. : SMD3005S

VEHICLE MAKE : HONDA HRV 1.5 DX CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 880.00	\$ 880.00
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
5	Rear Bumper Reflector RH	1	\$ 150.00	\$ 150.00
6	Rear Undercover Cover	1	\$ 280.00	\$ 280.00
7	Rear Tailgate Door	1	\$ 1,080.00	\$ 1,080.00
8	Rear Tailgate Door Lock	1	\$ 280.00	\$ 280.00
9	Rear Tailgate Door Rubber Seal	1	\$ 120.00	\$ 120.00
10	Rear HRV Emblem	1	\$ 80.00	\$ 80.00
11	Rear Honda Emblem	1	\$ 80.00	\$ 80.00
12	Rear i-Vtec Emblem	1	\$ 80.00	\$ 80.00
13	Rear / End Panel Garnish	1	\$ 200.00	\$ 200.00
14	End Panel	1	\$ 480.00	\$ 480.00
15	Rear Windscreen Molding	1	\$ 100.00	\$ 100.00
16	Rear Buzzer	1	\$ 110.00	\$ 110.00
17	Rear Exhaust	1	\$ 560.00	\$ 560.00
18	Rear Exhaust Rubber Mount	2	\$ 40.00	\$ 80.00
Total Spare Parts				\$ 4,670.00
	<u>SPECIAL NETT</u>			
19	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
20	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
	<u>LABOUR</u>			
21	Spray Painting Whole Rear include Blending	1	\$ 800.00	\$ 800.00
22	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 800.00	\$ 800.00
23	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
24	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
25	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
26	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
27	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2104-093

DATE : 30-Apr-2021

POLICY NO. : FWD PNPV2019-00011461-01

VEHICLE REG. NO. : SMD3005S

VEHICLE MAKE : HONDA HRV 1.5 DX CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,090.00
Amount Before Excess	\$ 7,000.00
Add GST @ 7%	490.00
Total Amount Payable	\$ 7,490.00