

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD137Z****AAD2104-***Not Notified*  
*1/1/2021*

Vehicle No.:

**29 APR 2021****SHD137Z**

Chassis No.:

VF1ABL15AUC282241

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

27/04/2021

Third Party Insurer :

**AIG**

Date of Registration :

01/09/2015

**PART****LIST**

- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 HEADLAMP RH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 WIPER RESERVOIR

\$	<i>Bulldo</i>	747.20	✓
\$	<i>Sn</i>	394.68	X
\$	<i>R</i>	663.70	X
\$	<i>Sn</i>	101.40	X
\$	<i>R</i>	437.10	X
\$	<i>Sn</i>	191.40	X
\$	<i>Lot</i>	743.60	✓
\$	<i>Sn</i>	207.21	X
\$	<i>Sn</i>	179.60	X
\$		<b>3,665.89</b>	
10%	\$	<b>366.59</b>	
\$		<b>3,299.30</b>	

**Special Nett**

- 1SET FENDER CLIP
- 1SET FENDER LINER CLIP
- 1 DOOR STICKER TRANSCAB
- 1 DOOR STICKER CLASSIC
- 1 BUMPER CLIP FRT
- 1 BUMPER RETAINER CLIP FRT
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1 BUMPER CLIP FRT
- 1 BUMPER GRILLE LOWER CLIP

\$	<i>na</i>	65.00	X
\$	<i>na</i>	60.00	X
\$	<i>na</i>	100.00	X
\$	<i>na</i>	100.00	X
\$	<i>na</i>	85.00	<i>66.50</i>
\$	<i>na</i>	70.00	} X
\$	<i>na</i>	33.00	
\$	<i>na</i>	10.00	
\$	<i>na</i>	20.00	
\$	<i>na</i>	10.00	
\$	<i>na</i>	20.00	
\$	<i>na</i>	85.00	
\$	<i>na</i>	70.00	

**Trans-cab Auto Services Pte Ltd**

AAD2104-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD137Z

TOTAL	\$	480.00
TOTAL PARTS	\$	3,779.30

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen  
Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *4401*

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of Parts,  
Adjust And Realign The Same

\$ 3,000.00 *2001*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ *4* 170.00 *X*

To transfer of bootlid fittings, attachments and  
perform water seepage test.

\$ *4* 170.00 *X*

To repair and realign rear exhaust pipe.

\$ *4* 170.00 *X*

To drop rear exhaust box, renew the same, to repair  
and realign centre exhaust pipe.

\$ *4* 170.00 *X*

To transfer of rear end panel fittings, attachment and  
perform water seepage test.

\$ *4* 170.00 *X*

To transfer of rear windscreen fittings and conduct  
water seepage test.

\$ *4* 170.00 *X*

To check steering geometry and computer wheel  
alignment

\$ *4* 220.00 *X*

**Trans-cab Auto Services Pte Ltd**

**AAD2104-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD137Z**

To Check Electrical Lighting Concerned. \$ 170.00 *201*

**TOTAL \$ 7,880.00**

**Over All Total \$ 14,958.60**

**(LUMP SUM)**

**Repair Days**

*20 DAYS*

*1 1/2 da*

*20 days*

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**