

Sin Motor Repairs
Block 176, #05-07, Sin Ming Drive, Sin Ming Auto Care
Singapore 575721
Tel: 64533908, 64596902 Fax: 64536602

G.S.T. REGISTRATION : 07683000D

ESTIMATE BILL 110/SM/2021

30/4/2021

Your Ref: SNM21D202497/GBH8013U/0w Ref!

THE INSURED / DRIVER :
ENG CHIN HUAT
30 JALAN SIAP
SINGAPORE 678561
MOBILE NO : 96675487

VEHICLE NO. SBV9989U
DATE OF ACCIDENT : 29/04/2021- 1405pm
ALONG JALAN SLAP
MODEL : MERZ E200
CHASIS NO. WDD2130422A139557

NAME OF INSURANCE: MSIG NSURANCE
POLICY NO. A 300409213 QMY
THIRD PARTY INSURANCE: CHINA TAIPING INSURANCE
AGAINST YOUR INSURED VEHICLE NO. GBH8013U

1)	REAR BUMPER	1615.32			
2)	BUMPER BRACKETS - 2PCS @ \$100*2		N/C CM	cls sn	200.00 X
3)	REAR BUMPER REINFORCEMENT			n	960.00 X
4)	BUMPER SIDE REFLECTOR - LH			sn	40.00 X
5)	REAR RESERVE SENSORS - 2PCS*209			sn	418.00 X
6)	TAIL LAMP - LH	841.		ca	920.00 ✓
7)	BUMPER MOULDING CHROME (BOTTOM) - LH			sn	370.00 X
8)	BUMPER RIVERT CLIPS 10PCS @\$7			re	70.00 ✓
2pc Tail lamp 1pc retain 083.00 CM ✓					
LABOUR CHARGES FOR THE FOLLOWING :-					

TO DETECT REAR RESERVE SENSOR	100.00	601
DISMANTLE AND RE-INSTALLATION ON REAR BUMPER ASSY, TAIL LAMP N RESERVE SENSOR	650.00	601
SPRAY PAINTING ON REAR BUMPER/SENSOR/RR FENDER/	780.00	601

TOUCH UP ON THE OTHERS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM :	\$6,848.00
LESS : -) 10%	-\$684.80
G-TOTAL :	\$6,163.20