



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 8886Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN	BROKEN	6,800.00	6,800.00
1	FRONT WINDSCREEN INNER SEAL	NECESSARY	650.00	650.00
1	FRONT PANEL	BROKEN	4,200.00	4,200.00
1	FRONT BUMPER	BROKEN	1,850.00	1,850.00
1	FRONT PANEL INNER STRUCTURE	* CHECK	2,350.00	-
2	FRONT WIPER ARM LH & RH @\$145.00	N/S BENT	290.00	145.00
2	FRONT WIPER ARM BLADE LH & RH @\$115.00	N/S BENT	230.00	115.00
1	FRONT CENTER PANEL	BROKEN	1,400.00	1,400.00
8	SEALANT @\$40.00	NECESSARY	320.00	320.00
1	ERP	NECESSARY	26.00	26.00
1	SCANIA EMBLEM	NECESSARY	350.00	350.00
1	SCANIA LOGO EMBLEM	NECESSARY	380.00	380.00
	LESS 10% DISCOUNT		-	-1,623.60
			18,846.00	14,612.40
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN.		1,000.00	800.00
	LABOUR CHARGES.		1,500.00	1,300.00
	SPRAY PAINTING.		1,000.00	800.00
			3,500.00	2,900.00
	GRAND TOTAL		22,346.00	17,512.40
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,115.00 NETT)			17,512.40

Report Ref No. CS/SMR21005372/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.