

C O N N E C T 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/PD8886Y/TPC

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

QUOTATION

Dear Sir,


Cost of Repair to Vehicle PD8886Y

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front windscreen	1	6,800.00	6,800.00
2.	Front windscreen inner seal	1	650.00	650.00
3.	Front panel	1	4,200.00	4,200.00
4.	Front bumper	1	1,850.00	1,850.00
5.	Front panel inner structure	1	2,350.00	2,350.00
6.	Front wiper arm LH & RH	2	145.00	290.00
7.	Front wiper arm blade LH & RH	2	115.00	230.00
8.	Front center panel	1	1,400.00	1,400.00
9.	Sealant	8	40.00	320.00
10.	ERP	1	26.00	26.00
11.	Scania emblem	1	350.00	350.00
12.	Scania logo emblem	1	380.00	380.00
13.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00
14.	Labour charges	1	1,500.00	1,500.00
15.	Spray painting	1	1,000.00	1,000.00
	SUB-TOTAL			S\$22,346.00

- Price b4 7% gst

Thank you.
Yours faithfully,



Winnie Chai
HP: 9850-9666

