

The Motor Claims Department
M/s United Overseas Insurance Ltd
3 Anson Rd #28-01
Springleaf Tower
Singapore 079909

Date : 29-April-2021

Not Notified
U/Ry &
Repair After Paint
Ex ?

Estimated cost of repair for vehicle no : EY1200S Porsche 911
Policy no: DHOM110167801901 Accident Date: 24.03.2021

Description	Quantity	Cost Price
LH door	1	\$ <i>B</i> 4,276.80 —
LH door outer handle assembly	1	\$ <i>CM</i> 909.48 —
LH door inner lock	1	\$ <i>Tn</i> 1,993.20 —
LH door outer window lower chrome trim	1	\$ <i>DI</i> 698.28 ✓
LH door inner window switch	1	\$ 356.40 ?
LH door frame weatherstrip	1	\$ <i>DI</i> 35.64 —
LH door striker	1	\$ 473.88 ?
LH rear trunk release handle	1	\$ 26.40 ?
LH rear fender carbon fibre panel	1	\$ <i>CM</i> 3,946.80 ✓
LH rear fender front panel	1	\$ <i>Bu</i> 3,762.00 ✓
LH rear fender paint chip protection sticker	1	\$ 1,056.00 ?
LH rear fender quarter glass rubber molding	1	\$ <i>Me</i> 310.20 ✓
LH rear fender quarter glass lower chrome trim	1	\$ 646.80 ?
RH side skirt	1	\$ <i>MI</i> 3,946.80 ✓
RH side skirt mounting (1 set)	1	\$ <i>Me</i> 579.48 —
RH door sill black trim	1	\$ <i>Bu</i> 315.48 ✓
RH rear wheel rim	1	\$ <i>DI</i> 6,600.00 —
LH rear wheel rim	1	\$ <i>B</i> 6,600.00 —
RH rear axle trailing arm	1	\$ 5,940.00 ?
LH rear axle trailing arm	1	\$ <i>B</i> 5,940.00 ✓
RH rear axle strut	1	\$ 110.88 ?
LH rear axle strut	1	\$ 110.88 ?
RH rear wheel bearing	1	\$ <i>Me</i> 112.86 —
LH rear wheel bearing	1	\$ <i>Me</i> 112.86 —
RH rear shock absorber coilover	1	\$ 4,092.00 ?
LH rear shock absorber coilover	1	\$ <i>B</i> 4,092.00 ✓
RH rear drive shaft	1	\$ 1,107.48 ?
LH rear drive shaft	1	\$ 1,107.48 ?
Rear stabilizer bar	1	\$ 297.00 ?
LH rear stabilizer bar link	1	\$ 231.00 ?
RH rear stabilizer bar link	1	\$ 231.00 ?
RH rear fender inner oil tank	1	\$ 2,508.00 ?
RH engine oil line	1	\$ 328.68 ?
Exhaust muffler cover	1	\$ <i>DI</i> 434.28 ✓
Rear bumper	1	\$ <i>Se</i> 5,346.00 X
RH undercarriage panel	1	\$ 3,681.48 ?
RH door sill panel	1	\$ <i>B</i> 891.00 ✓

	\$	73,208.52
Add 15%	\$	10,981.28
	\$	84,189.80

Rear tyres (Michelin 265/40ZR17)	2	S. Nett	\$	<i>Pu</i> 700.00	<i>30</i>
LH rear quarter glass sealant	1	S. Nett	\$	<i>M</i> 40.00	<i>✓</i>
LH rear quarter glass inner rubber seal	1	S. Nett	\$	<i>M</i> 28.00	<i>✓</i>
Engine oil	1	S. Nett	\$	90.00	<i>7</i>
To remove and reinstall LH rear quarter glass to facilitate repairs			\$	100.00	<i>60</i>
To remove, check and reinstall RH & LH rear suspension system and replace damaged parts			\$	400.00	<i>30</i>
To perform computerised wheel alignment			\$	65.00	<i>✓</i>
To remove and reinstall RH & LH front seats, rear seats, floor carpet to facilitate repairs on RH undercarriage panel			\$	400.00	<i>200</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality			\$	100.00	<i>60</i>
To remove and replace RH rear fender inner engine oil tank and oil line. To refill engine oil			\$	150.00	<i>7</i>
To remove rear damaged parts, and cut out affected body panels, to reweld, and rejoin LH rear carbon fibre fender, LH rear fender frontal panel, RH floor panel, to replace LH door and remove and refit door trim board, lock, window glass and regulator, to adjust body and door alignment			\$	6,500.00	<i>360</i>
To spray paint affected LH and RH side and inner damaged portion inclusive of preparatory works and material. To reapply LH rear fender paint chip protection sticker			\$	1,400.00	<i>120</i>
Towing charges (king dolly)			\$	(<i>Bill</i>) 120.00	<i>✓</i>
			\$	94,282.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: