

REPAIR DETAILS

SLX 6621A

supp 1

Reference**Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 06 May 2021)

Parts: 143

TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SLX6621A/06/05/2021 12:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER INNER SPONGE ✓ cra	0.00	0.00	*75.00F
2	1		*1 PC FRT TOP PANEL ✓ buc	0.00	0.00	*100.00F

F=Franchise part

Total Parts (S\$)

175.00

Cheng Hoe Motor Pte Ltd/SLX6621A/06/05/2021 12:39 Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SLX6621A/06/05/2021 12:39 Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >