

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : TAX/04/21/2075 Date: 12th May 2021

Our Ref : CS/SMR21005381/R1uf3e2

M/s Smrt Automotive Services Pte Ltd

60 Woodlands Industrial Park E4 Singapore 757705 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBK 7934C INSURED VEHICLE: SHB 5843X ACCIDENT ON 26/04/2021

Instruction was received to inspect the vehicle Reg. No. FBK 7934C. The inspection was conducted on 04/05/2021 at the premises of M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1, #01-24, Singapore 408934.

The following vehicle information was recorded:

Registration Number : FBK 7934C

Make/Model : Honda Wave 125R SM/T

Year of Registration : 2006 Body Colour : Orange

Chassis Number : NF125MP0060235

Engine Capacity : 125 cc

The vehicle sustained damages at the o/s, n/s body and front portion. (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**Total Loss**".

Market Value S\$ 100.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 24.00)

Nett Liability S\$ 76.00

Vehicle Inspected By:

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

KKLAII

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust),MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.