

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0372/2021/HR
DATE : 29-Apr-21
WIP :

VEHICLE NOT IN WORKSHOP. SURVEY TBC

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

**5 days exclude 1
Johnny Boo 21 J**

OWNER'S NAME : MR. THAM JIA YONG, KEVIN
ADDRESS : 606C TAMPINES ST 61
#09-380
SINGAPORE 523606
TELEPHONE : HP +65 81881080
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070055890
VEHICLE NO : **SMT 1833 Y**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 30/3/2020
ENGINE NO : CZD 891778
CHASSIS NO : WAUZZZF36L1079544
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Apr-21
PLACE OF ACCIDENT : NEAR 605 TAMPINES STREET 61, SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 1833 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE & REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$	280.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$	280.00
3	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS FRONT DOOR, LHS REAR FENDER AND DOOR ENTRANCE. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	750.00
4	TO RESPRAY LHS REAR DOOR, LHS FRONT DOOR, LHS REAR FENDER, DOOR HANDLE AND DOOR ENTRANCE.	\$	3,600.00	\$	1,750.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 7,272.00	\$	3,252.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 1833 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - LH	1	\$ 2,909.00	\$	2,327.20
2	REAR DOOR OUTER DOOR SEAL - LH	1	\$ 135.00	\$	108.00
3	REAR DOOR CATCH	1	\$ 120.00		
4	REAR DOOR INNER SEAL	1	\$ 191.00		
5	REAR DOOR SILL PANEL SEAL - LH	1	\$ 135.00		
6	REAR DOOR HANDLE - LH	1	\$ 198.00	\$	158.00
7	REAR DOOR HOUSING CAP - LH	1	\$ 27.00	\$	21.60
8	REAR DOOR WINDOW REGULATOR - LH	1	\$ 282.00		
9	REAR DOOR WINDOW REGULATOR MOTOR - LH	1	\$ 271.00		
10	REAR DOOR ARCH COVER - LH	1	\$ 257.00	\$	205.20
11	REAR WHEEL ARCH COVER - LH	1	\$ 268.00	\$	214.40
12	FRONT DOOR ARCH COVER - LH	1	\$ 268.00		
12	SUNDRIES		\$ 250.00	\$	3.84
TOTAL SPARE PARTS		:	\$ 5,311.00	\$	3,038.24
TOTAL LABOUR CHARGES		:	\$ 7,272.00	\$	3,252.00
GRAND TOTAL		:	\$ 12,583.00	\$	6,290.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-01/06/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT