

CHOO MOTOR SPRAY PAINTER

1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: SLQ 3535Y

* H51A070ng

not Authorized
Man

3/5/21

1/5 @ 5000 / 4 days.

1PC	FRONT DOOR O/S	
1PC	FRONT DOOR OUTER PROTECTOR O/S	380.20
1SET	FRONT DOOR FRAME BLACK STICKER O/S	
1PC	FRONT DOOR INNER RUBBER O/S	
1PC	REAR DOOR O/S	1280.10
1PC	REAR DOOR OUTER PROTECTOR O/S	299.50
1SET	REAR DOOR OUTER FRAME BLACK STICKER O/S	
1PC	REAR DOOR INNER RUBBER O/S	188.10
1PC	REAR DOOR GLASS OUTER MOULDING O/S	
2PCS	REAR DOOR HINGES @\$105.00	
1PC	REAR DOOR CHECKER O/S	
1PC	ROCKER PANEL GARNISH O/S	681.10
1PC	REAR FENDER O/S	
1PC	REAR FENDER OUTER GARNISH O/S	322.50
1PC	REAR SHOCK ABSORBER O/S	
1PC	REAR WHEEL HUB BEARING O/S	820.00
1PC	REAR KNUCKLE ARM O/S	655.20
1PC	REAR TRAILING ARM O/S	380.50
1PC	REAR CROSS MEMBER	
1PC	REAR BUMPER	
1PC	REAR BUMPER PAD	456.10
1SET	REAR BUMPER CLIPS	
1PC	REAR SPORT RIM O/S 20 INCH	

R	\$1,819.20	X
Torn	\$822.30	✓
11	\$85.00	X
11	\$211.20	X
TD	\$1,699.20	✓
Dis	\$745.30	✓
ner	\$85.00	✓
ner	\$215.20	✓
11	\$145.50	X
11	\$210.00	X
11	\$151.00	X
grend/torn	\$981.20	✓
R	\$1,219.10	X
grend	\$485.20	✓
11	\$392.20	X
Dampes	\$650.00	✓
Surf	\$855.20	✓
Surf	\$615.20	✓
11	\$1,455.80	X
R	\$981.20	X
grend	\$655.20	✓
ner	\$50.00	✓
dent/wegd	\$1,800.00	880s/n
	\$16,329.20	

(257)

TO CHECK WIRING	\$50.00	-20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	-50
TO TRANSFER O/S DOOR MECHANISM	\$180.00	-60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	X
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$280.00	120
TO DISMANTLE & REFIX FUEL TANK	\$100.00	X
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	400
TO PUTTY & SPRAY PAINTING	\$1,500.00	700
TOTAL	\$19,759.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 5298.30
252
3973.72