

新福德車廠私人有限公司 Adrian LLC Ally NEW HOCK TECK MOTOR PTE. LTD. Ally

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Email: admin@nhtmotor.com Website: www.nhtmotor.com Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

03/05/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 11/01/2021

Estimated repair cost for vehicle no: SLR6471Y HONDA HRV 1.5 DX CVT

CHASSIS: JHMRU1810GX202874

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER Detro		\$495.80
2	1	FRONT BUMPER LOWER LIP Tom		\$351.00
3	1	FRONT BUMNPER SIDE RETAINER RH Men		\$27.10
4	1	FRONT BUMPER REINFORCMENT Dented		\$321.00
5	1	FRONT BUMPER FOG LAMP COVER RH		\$45.00
6	1	FRONT BUMPER FOG LAMP RH Could		\$327.70
7	1	RH FRONT HEADLAMP and		\$1,820.90
8	1	RH FRONR HEADLAMP LOWER BRACKET Could		\$45.00
9	1	RH FRONT FENDER Hem	-	\$582.00
10	1	RH FRONT FENDER INNER COWLING New		\$131.00
11	1	RH FRONT FENDER OUTER GARNISH		\$166.00
12	1	FRONT GRILLE Cauded		\$385.00
13	1	FRONT SUPPORT PANEL TOP GARNISH 7 Ld m		\$95.30
14	1	FRONT SUPPORT PANEL		\$576.20
15	1	Washer Tank Crubo	TOTAL :-	\$5,369.00
13	1	69.50 / 4 126.50	LESS 20	\$1,073.80
	330(-52SUB-TOTAL:		\$4,295.20	

TPALG.

Jaslin.

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT NUMBER PLATE WITH CASING WILL		\$60.00
2	1	FRONT BUMPER CLIPS NG.		\$80.00
3	1	FRONT GRILLE CLIPS MIN		\$80.00 ×
4	4	FRONT FENDER INNER COWLING CLIPS		\$80.00 4
		* 7	TOTAL:	\$300.00

30

TOTAL PARTS:

\$4,595.20

Labour charges

To check wiring

\$80.00 30

Tuff kote

\$200.00 ×

Panel beating

930

\$1,000.00 400

Spray painting

\$1,200,00 400.

Subtotal:-

\$2,480.00

Total:-

\$7,075.20

total: 4261.52 1/s, 3.4Kc 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: