

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email:atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Steve (LKK)

W/P

3/5/21

L/S

Resurvey After Spray
4 repair days

Date of Estimate: 05.08.2019
Vehicle No: PA8722C
Owner: DEWAY TRAVEL & COACH PTE LTD
Date of Accident: 08.07.2019
Make & Model: TOYOTA HIACE COMMUTER GL 3.0A
Chassis No : KDH2230005230

ESTIMATE FOR ACCIDENT VEHICLE NO PA8722C

PARTS

1	1 Front door LH — DD	\$1,529.00	1218 —
2	1 Front door weatherstrip LH x nn	\$236.00	
3	1 Front door hinge top LH x nn	\$115.00	
4	1 Front door hinge bottom LH x nn	\$115.00	
5	1 Front door step garnish LH(repair) x nn	\$0.00	
6	1 Front door A pillar lower panel LH(repair) x R	\$0.00	
7	1 Front bumper — BR	\$890.00	575 —
8	1 Front bumper bracket LH — BR	\$179.00	120 —
9	1 Headlamp LH — BR	\$950.00	860 —
10	1 Headlamp bracket LH x nn	\$156.00	
11	1 Front corner panel LH x R	\$267.00	
12	1 Side mirror assy LH x nn	\$236.00	
13	1 Side mirror square LH x nn	\$108.00	
14	1 Blindspot mirror round LH x nn	\$89.00	
SUB TOTAL		\$4,870.00	
LESS 25%		\$1,217.50	
DISCOUNTED SUB TOTAL		\$3,652.50	

2773
- 25%
2079.75

S. NETT ITEM

1	1set Front bumper clips	\$50.00	30 —
2	1 Front door RH company logo RH	\$100.00	80 —
SUB TOTAL		\$150.00	
LESS 0 %		\$0.00	
DISCOUNTED SUB TOTAL		\$150.00	

110

LABOUR

1	Panel beating for replace and repair affected parts	\$600.00	500 —
2	Spray painting on accident areas X 3 colours	\$800.00	700 —
3	Wiring charges	\$100.00	30 —
4	Apply undercoating to above affected areas	\$150.00	30 —
SUB TOTAL (LABOUR)		\$1,650.00	

1260

= 3449.75

SUB TOTAL (PARTS)	\$3,652.50
S. NETT (PARTS)	\$150.00
SUB TOTAL (LABOUR)	\$1,650.00
ESTIMATED GRAND TOTAL	\$5,452.50

L/S - 2759.80

= 2750