

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT

*Not Authorized
1/1/2021
Resurvey After Rain*

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: GBB2280K
MODEL : MITSUBISHI CANTER
POLICY NO : D18MCV0001978_82
CHASSIS NO : FB70BBA10637

Date: 04/05/2021
Page : 1 of 2

DATE / TIME OF ACCIDENT: 03/05/2021 Time: 12:38Hrs at BALMORAL PARK
THIRD PARTY VEHICLE NO: SJS1912T

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Amount
S/N			S\$	S\$
1	Front Headlamp Set RH	1	619.00	NN 619.00 ✓
2	Front Signal Lamp RH	1	206.00	RN 206.00 ✓
3	Front Side Lamp	1	139.00	RN 139.00 ✓
4	Front Bumper	1	833.00	RN 833.00 ✓
5	Front Bumper Retainer	1	92.00	NSP 92.00 X
6	Front Fender RH	1	398.00	RN 398.00 ✓
7	Stepper Garnish RH	1	346.00	CM 346.00 ✓
8	Door RH	1	1,910.00	RN 1,910.00 ✓
9	Sticker	1	60.00	na 25m 60.00
			25f	
Sub-Total:				4,603.00
Total Parts :				4,603.00

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)	50d	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	550l	1,500.00
3	Dismantle and transfer door fittings and mechanism to new door	60l	250.00
4	Provide skill labour to disconnect and check electrical wiring for signal light (Front Headlight)	20l	150.00
5	Provide skill labour to wheel alignment	na	300.00 X
6	Provide skill labour to check undercarriage	na	300.00 X

Total Labour:

Total Parts & Labour:
GST 7%
Grand Total:

4,000.00
8,603.00
602.21
9,205.21

ACCIDENT VEHICLE OF : GBB2280K

Estimate Repair Duration

25 days
4 days

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR:

Survey attended by:

Name : Kenneth
Company : LKK
Date : 5/5/21
Time :
Contact No: 98910663
Email :

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: