

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21005435/UQF3E2

**Date:** 22/06/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00046482001  
Claimant Vehicle No: SMK2665G Insured Vehicle No: YP3269S  
Date of Loss: 01/05/2021 Nature of Claim: TP Claim No: SNM21D202525/C02/LOWCT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK2665G**  
Make & Model: TOYOTA C-HR, 1.2 TURBO LUXURY (A) Engine No: 8NRU190573  
Reg. Date: 02/04/2019 (Man. Year: 2018) Chassis No: JTNKY3BX101007512  
Colour: White Odometer: 19610 km  
Engine Capacity: 1197 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17  
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,795.00	1,927.00	1,868.00	49.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,428.45	1,220.94	207.51	14.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,223.45</b>	<b>3,147.94</b>	<b>2,075.51</b>	<b>39.73</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>365.64</b>	<b>220.36</b>	<b>145.28</b>	<b>39.73</b>
<b>Nett Amount (S\$)</b>	<b>5,589.09</b>	<b>3,368.30</b>	<b>2,220.79</b>	<b>39.73</b>

### INSPECTION

Date of Assignment: 04/05/2021 Present Location: Jin Auto Services Pte Ltd (Defu)  
Date Inspected: 04/05/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195  
Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 Jun 2021)

**Parts:**            M1-SUV      TOYOTA C-HR 1.2 TURBO LUXURY (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMK2665G)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	-	*20.00 F
2	1		*SENSOR COVER	Necessary	-	*72.00 F
3	1		*TAILGATE TOP GARNISH	Cracked	-	*160.00 F
4	1		*PARTS		3,795.00 F	*1,675.00 F
					<b>Total Parts (S\$)</b>	<b>3,795.00      1,927.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	655.20	541.80
2	SPRAY PAINT	New	773.25	679.14
			<b>Gross Labour Cost (S\$)</b>	<b>1,220.94</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >