

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21005441/KBA3Q2

Date:

14/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MCV0000229_01

Claimant Vehicle No : GBJ271H**Insured Vehicle No :**

YN3402J

Date of Loss: 21/04/2021

Nature of Claim:

TP

Claim No:

MCV2021D0001974

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ271H**

Make & Model: MERCEDES-BENZ CITAN 109, 1.5 CDI EL 5MT 6DL (A)

Engine No:

K9KE628D626524

Reg. Date: 05/12/2018 (Man. Year: 2018)

Chassis No:

WDF4156052U254497

Colour: Silver

Odometer:

61708 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Gremax 7 mm

Rear Left Side:

Gremax 8 mm

Front Right Side: Gremax 7 mm

Rear Right Side:

Gremax 8 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,030.75	572.00	2,458.75	81.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,265.00	1,375.00	52.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,670.75	1,837.00	3,833.75	67.61
+ GST 7.00/7.00% (S\$)	396.95	128.59	268.36	67.61

Nett Amount (S\$)	6,067.70	1,965.59	4,102.11	67.61
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,453.04		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment: 04/05/2021

Date Inspected: 04/05/2021

Estimated Period of Repair: 4.0 days

Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Jun 2021)	
Parts:	N/A	MERCEDES-BENZ CITAN 109 1.5 CDI EL 5MT 6DL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ271H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NPA)	Repair	0.00 FN	*- FN
2	1		*REAR BUMPWR PAD	Dented / Cut	580.00 FN	*580.00 FN
3	1		*REAR BUMPWR SIDE RETAINER -RH	Serviceable	215.00 FN	*- FN
4	1		*REAR BUMPER CLIPS (15 PCS)	Necessary	74.25 FS	*50.00 FS
5	1		*REAR FENDER -RH	Repair	2,490.00 FN	*- FN
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (S\$)	3,359.25
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	328.50
					Total Parts (S\$)	3,030.75
						630.00
						572.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	0.00
2	TO CHECK AND RECIFY WIRING SYSTEM	New	80.00	15.00
3	TO PANEL BEAT AND STRAIGHTEN RH REAR CHASDID FRAME ,RH REAR FENDER INNER PANEL,TO CUT AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	800.00	450.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	450.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANEL	New	80.00	0.00
6	TO SUPPLY ARTWORK AND PARTE DECAL ON RH REAR FENDER AND REAR BUMPER	New	580.00	350.00
Gross Labour Cost (S\$)			2,640.00	1,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >