



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

ESTIMATE

NO : QUOT202105-000002(00)

DATE : 03/05/2021

POLICY NO : 999995580

VEH REG NO : GBJ271H

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR

CHASSIS NO : WDF4156052U254497

ENGINE NO : K9KE628D626524

REG. DATE : 2018

YOUR REF NO : YN3402J

CLAIM TYPE : THIRD PARTY

TP INS. CO. : INDIA INTERNATIONAL INSURANCE PTE LTD

ACCIDENT DATE : 21/04/2021

TP VEH REG NO : YN3402J

Not authorized

Repair after pain

4 days

Estimate Repair Cost to Vehicle No : GBJ271H

Description	Quantity	Unit Price	Amount
NET PRICE		S\$	S\$
1 Rear bumper	1	0.00	0.00
2 Rear bumper pad	1	580.00	580.00
3 Rear bumper side retainer - RH	1	215.00	215.00
4 Rear bumper clips	15	5.50	82.50
5 Rear fender - RH	1	2,490.00	2,490.00
			3,367.50
		Less 10%	336.75
			3,030.75
LABOUR			
6 To remove and refit rear bumper sensor	1	100.00	100.00
7 To check and rectify wiring system	1	80.00	80.00
8 To panel beat and straighten RH rear chasidid frame, RH rear fender inner panel, to cut and align where necessary, to refit and adjust the same	1	800.00	800.00
9 To putty and spray paint on affected areas	1	1,000.00	1,000.00
10 To apply rust-proofing on replaced and repaired panel	1	80.00	80.00
11 To supply artwork and paste decal on RH rear fender and rear bumper	1	580.00	580.00
			2,640.00
		TOTAL	S\$ 5,670.75
		ADD GST @ 7%	396.95
		GRAND TOTAL	S\$ 6,067.70

SINGAPORE DOLLAR SIX THOUSAND SIXTY SEVEN AND CENTS SEVENTY ONLY

LKK Auto Consultants hence notify

the Repairer in the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE