

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	22K

TO: AIG
Vehicle No : SCK 899 E
Make & Model : BMW 520I
DATE: 3/5/2021

2013

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BOOT LID 1680.00	1	\$ 1,680.00	\$ 1,680.00	DDV✓
2	BOOT LID LOGO 39.00	1	\$ 96.00	\$ 39.00 96.00	NEC✓
3	BOOT LID EMBLEM (520I) 64.10	1	\$ 97.00	\$ 64.10 97.00	NDX✓
4	BOOT LID REFLECTOR	2	\$ 658.00	\$ 1,316.00	NDX✓
5	BOOT LID INNER LOCK 315.00	1	\$ 552.00	\$ 315.00 552.00	NDX✓
6	BOOT LID LOCK CATCH	1	\$ 66.00	\$ 66.00	NDX✓
7	BOOT LID WEATHERSTRIP 126.80	1	\$ 217.90	\$ 126.80 217.90	NDX✓
8	BOOT LID INNER TRIM	1	\$ 255.00	\$ 255.00	NDX✓
9	BOOT LID SIDE STOPPER	2	\$ 90.00	\$ 180.00	NDX✓
10	BOOT LID DETECTOR 280.00	1	\$ 321.00	\$ 280.00 321.00	BRV✓
11	REAR BUMPER 1531.22	1	\$ 1,782.00	\$ 1,782.00	BRV✓
12	REAR BUMPER SIDE BRACKET (PLASTIC) 228.00	2	\$ 114.00	\$ 228.00	BRV✓
13	REAR BUMPER CENTER BRACKET (CENTER) 150.00	1	\$ 298.00	\$ 298.00	BRV✓
14	REAR BUMPER BOLT COVER	2	\$ 59.00	\$ 118.00	NNX✓
15	REAR BUMPER REINFORCEMENT 418.60	1	\$ 791.00	\$ 791.00	BTV✓
16	REAR BUMPER TOWING COVER	1	\$ 39.60	\$ 39.60	NNX✓
17	REAR BUMPER SENSOR 450.90 2	4	\$ 225.45 314.00	\$ 1,256.00	SCV✓
18	REAR BUMPER SENSOR WIREHARNESS 165.20	1	\$ 698.00	\$ 698.00	WTV✓
19	REAR BUMPER SENSOR HOLDER 124.80	4	\$ 31.20	\$ 124.80	NEC✓
20	REAR BUMPER SENSOR BRACKET	1	\$ 120.00	\$ 120.00	NNX✓
21	REAR BUMPER LOWER GARNISH (CENTER) 109.35	1	\$ 195.00	\$ 195.00	BRV✓
22	REAR BUMPER LOWER GARNISH (SIDE) 106.00	1	\$ 258.00	\$ 258.00	BRV✓
23	REAR BUMPER REFLECTOR 92.40	2	\$ 46.20 178.00	\$ 356.00	BRV✓
24	CONTROL SMART OPENER SENSOR 2 314.72	1	\$ 384.00	\$ 384.00	SCV✓
25	CONTROL SMART OPENER SENSOR 1 414.72	1	\$ 526.00	\$ 526.00	SCV✓
26	CONTROL SMART OPENER SENSOR UNIT ECU 225.00	1	\$ 548.00	\$ 225.00 548.00	BRV✓

225.00

125.00

27	TAIL LAMP	1160.00	2	\$ 550.00 754.00	\$ 1,508.00	BR
28	TAIL LAMP GARNISH	179.80	2	\$ 89.90 125.00	\$ 250.00	BRV
29	REAR END PANEL	581.30	1	\$ 581.30 860.00	\$ 860.00	DDV
30	REAR END PANEL TOP GARNISH	225.00	1	\$ 346.00	\$ 346.00	BRV
31	REAR FLOOR TOP BOARD		1	\$ 689.00	\$ 689.00	
32	REAR FENDER INNER TRIM		2	\$ 458.00	\$ 916.00	
33	REAR FENDER INNER SHIELD		2	\$ 219.00	\$ 438.00	
34	REAR EXHAUST PIPE		1	\$ 1,280.00	\$ 1,280.00	ND X
35	REAR EXHAUST MOUNTING		2	\$ 60.00	\$ 120.00	
36	REAR EXHAUST PIPE BRACKET		1	\$ 98.00	\$ 98.00	
37	REAR EXHAUST HEAT PLATE	197.90	1	\$ 197.90 479.58	\$ 479.58	DRV

Subtotal : \$ 19,487.88

Less 5% \$ 974.39

Parts Total : \$ 18,513.49

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00	
2	BOOTLID SEALANT	1	\$ 80.00	\$ 80.00	NN X
3	TAIL LAMP CLIP	1	\$ 30.00	\$ 30.00	
4	REAR FENDER INNER TRIM CLIPS	1	\$ 50.00	\$ 30.00 50.00	NCC
5	REAR FENDER INNER SHIELD CLIPS	1	\$ 50.00	\$ 50.00	NNX
6	REAR BUMPER CLIP	1	\$ 60.00	\$ 30.00 60.00	NCC
8	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 30.00 50.00	NCC
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 80.00 150.00	NCC
10	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00	NNX
11	REAR FLOOR TOOLS BOX SEALANT	1	\$ 150.00	\$ 150.00	NN X
12	REAR EXHAUST CHROME HEAD	2	\$ 400.00	\$ 800.00	
				170	

SPECIAL NETT \$ 1,720.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	800.00 ✓ \$ 1,600.00
TO SPRAY PAINT AFFECTED AREA	800.00 \$ 1,600.00
TUFF COAT	NN X \$ 200.00
WIRING CHECK	30.00 \$ 100.00
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	100.00 \$ 350.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	120.00 \$ 150.00
TRANFER BOOTLID MECHANISM	80.00 \$ 150.00

CONDUCT WATER LEAKAGE TEST	NNX	\$ 450.00
REMOVE AND REFIX REAR EXHAUST PIPE	150.00	\$ 350.00
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NNX	\$ 600.00
		2080.00
LABOUR TOTAL		\$ 5,250.00

	Total Parts Cost	\$ 20,233.49
	Total Labour Cost	\$ 5,250.00
	Total Repair Cost	\$ 25,483.49

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

97361577

Survey
5/5/2021
1430 hrs
TGLim

Resurvey on the
same day.

Lump sum repair

Repair days 6

Email teowquan@lkk auto .com

PARTS	8663.82
SN	170.00
LABOUR	2080.00
	10,913.82
@20%	2182.76
	8731.06

4/5 8750/2

TGLim

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: