

Survey 5/5/2021
 Resurvey 6/5/2021
 TCU line 1230hrs
 TCU line 1330hrs

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No: SMD5213U
 Model and make: Hyundai Elantra
 Chassis No: KMHD841CMJU729701

Qty Spare Parts

List Price (\$) 2018

1	Rear bumper	\$	✓ 459.40	BRV
1	Rear bumper lower cover	\$	✓ 250.10	DB ✓
1	Rear bumper RH side retainer	\$	✓ 44.30	} NEC ✓
1	Rear bumper LH side retainer	\$	✓ 44.30	
1	Rear bumper reinforcement	\$	✓ 294.80	BT ✓
2	Rear bumper reinforcement upper brackets	\$	16.00	} NDX
3	Rear bumper reinforcement lower brackets	\$	24.00	
1	Rear bumper inner sponge	\$	108.00	NSX
1	Rear bumper RH reflector	\$	✓ 40.80	BR ✓
1	Rear bumper LH reflector	\$	40.80	NDX
1	Bootlid	\$	1588.00	1,782.40 DD ✓
1	Bootlid RH hinge	\$	94.30	} NDX
1	Bootlid LH hinge	\$	94.30	
1	Bootlid lock	\$	118.20	} NDX
1	Bootlid lock catch	\$	28.60	
1	Bootlid centre emblem	\$	✓ 28.00	} NEC ✓
1	Bootlid "Elantra" emblem	\$	✓ 48.80	
1	Bootlid "S" emblem	\$	✓ 32.80	NEC ✓
1	Bootlid RH lamp assy	\$	284.90	} NDX
1	Bootlid LH lamp assy	\$	284.90	
1	Bootlid weatherstrip	\$	92.50	NDX
1	End panel	\$	✓ 454.60	DD ✓
1	End panel inner garnish	\$	✓ 59.80	BR ✓
1	Smart entry sensor	\$	✓ 40.50	BR ✓
1	RH taillamp assy	\$	✓ 362.80	} BR ✓
1	LH taillamp assy	\$	✓ 362.80	

\$ 5,492.70
 -20% \$ 1,373.18
 \$ 4,119.53

Qty Spare Parts

Special Nett (\$)

1set	Rear bumper clips	nec	\$ 30.00	60.00
1set	Rear bumper reverse sensor	shorted	\$ 20.00	280.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 600.00	900.00 /
Spray painting on affected panels	\$ 600.00	1,000.00 /
Check wiring and lighting system	\$	50.00 N/A
Apply rust coating on affected areas	\$	70.00 N/A
Remove and replace rear bumper reverse sensors	\$ 60.00	70.00 /
Remove and replace rear inner trims and garnish to assist repairs	\$	200.00 N/A
Total:	\$	6,759.53

Lump sum repair
Repair Days 5

PARTS	3499.60
SN	230.00
LABOUR	1260.00
	4989.60
@ 2%	997.92
	3991.68

L/S 4000/2

Tekin M
14/5/2021

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: