

Survey
5/5/2021
TCLIM Lin
1230hrs

Resurvey
6/5/2021
TCLIM
1330hrs

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No: **SMD5213U**
Model and make: **Hyundai Elantra**
Chassis No: **KMHD841CMJU729701**

Qty Spare Parts

List Price (\$) **2018**

1	Rear bumper	\$	✓ 459.40	BRV
1	Rear bumper lower cover	\$	✓ 250.10	DB ✓
1	Rear bumper RH side retainer	\$	✓ 44.30	} NEC ✓
1	Rear bumper LH side retainer	\$	✓ 44.30	
1	Rear bumper reinforcement	\$	✓ 294.80	BT ✓
2	Rear bumper reinforcement upper brackets	\$	16.00	} NDX
3	Rear bumper reinforcement lower brackets	\$	24.00	
1	Rear bumper inner sponge	\$	108.00	NSX
1	Rear bumper RH reflector	\$	✓ 40.80	BR ✓
1	Rear bumper LH reflector	\$	40.80	NDX
1	Bootlid	\$	1588.00	1,782.40 DD ✓
1	Bootlid RH hinge	\$	94.30	} NDX
1	Bootlid LH hinge	\$	94.30	
1	Bootlid lock	\$	118.20	} NDX
1	Bootlid lock catch	\$	28.60	
1	Bootlid centre emblem	\$	✓ 28.00	} NEC ✓
1	Bootlid "Elantra" emblem	\$	✓ 48.80	
1	Bootlid "S" emblem	\$	✓ 32.80	NEC ✓
1	Bootlid RH lamp assy	\$	284.90	} NDX
1	Bootlid LH lamp assy	\$	284.90	
1	Bootlid weatherstrip	\$	92.50	NDX
1	End panel	\$	✓ 454.60	DD ✓
1	End panel inner garnish	\$	✓ 59.80	BR ✓
1	Smart entry sensor	\$	✓ 40.50	BR ✓
1	RH taillamp assy	\$	✓ 362.80	} BR ✓
1	LH taillamp assy	\$	✓ 362.80	

\$ 5,492.70
-20% \$ 1,373.18
\$ 4,119.53

Qty Spare Parts

Special Nett (\$)

1set	Rear bumper clips	\$	30.00	60.00
1set	Rear bumper reverse sensor	\$	20.00	280.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 ~~900.00~~ ✓

Spray painting on affected panels

\$ 600.00 ~~1,000.00~~ ✓

Check wiring and lighting system

\$ ~~50.00~~ N/A ✓

Apply rust coating on affected areas

\$ ~~70.00~~ N/A ✓

Remove and replace rear bumper reverse sensors

\$ 60.00 ~~70.00~~ ✓

Remove and replace rear inner trims and garnish to assist repairs

\$ ~~200.00~~ N/A ✓

Total:

\$ 6,759.53

Lump sum repair
Repair Days 5

PARTS	3499.60
SN	230.00
LABOUR	1260.00
	4989.60
@ 2%	997.92
	3991.68

L/S 4000/2

Tekin M

14/5/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: