

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM CHIN PONG
15 DA SILVA LANE
SINGAPORE 549806

Estimate No: MC1901915
Date: 03 May 2021
Policy No: P10225813R01
Veh Reg No: SKU8698T
Make/Model: TOYOTA COROLLA
ALTIS CLASSIC 1.6 CVT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 02/05/2021
TP Veh Reg No: SKG7890J

*Not Notified
11 Rm @ 4600.
Returning After Repair*

5 days

Estimate Repair Cost to Vehicle No :SKU8698T

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 FRONT BUMPER	1 PC	531.10	X
2 FRONT BUMPER SIDE RETAINER RH	1 PC	85.50	X
3 FRONT BUMPER CLIPS	10 PC	45.00	1
4 FRONT FENDER RH	1 PC	908.70	✓
5 FRONT FENDER COWLING RH	1 PC	209.10	X
6 FRONT FENDER COWLING CLIPS	8 PC	17.68	X
7 FRONT FENDER DUAL VVTI LOGO	1 PC	45.19	✓
8 FRONT DOOR RH	1 PC	1,260.00	X
9 SIDE MIRROR ARM WITH SIGNAL LAMP RH	1 PC	1,257.00	X
10 SIDE MIRROR COVER RH	1 PC	109.20	X
11 FRONT WHEEL BEARING RH	1 PC	167.30	✓
12 FRONT WHEEL HUB RH	1 PC	261.30	X
13 FRONT LOWER ARM RH	1 PC	732.50	✓
14 FRONT KNUCKLE ARM RH	1 PC	628.40	✓
15 FRONT SHOCK ABSORBER RH	1 PC	438.30	✓
16 FRONT SHOCK ABSORBER TOP MOUNTING RH	1 PC	219.10	X
		6,915.37	
	Less 25%	1,728.84	5,186.53
Special Nett			
17 SPORT RIM RHF	1 PC	2,010.70	✓
		2,010.70	
	Less 25%	502.68	1,508.03
18 TYRE RHF - CHECK PRICE	1 PC	0.0000	
		0.00	0.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
20 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60/
21 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	80.00	X
22 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	250.00	200/
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM CHIN PONG
15 DA SILVA LANE
SINGAPORE 549806

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 02/05/2021
TP Veh Reg No: SKG7890J

Estimate No: MC1901915
Date: 03 May 2021
Policy No: P10225813R01
Veh Reg No: SKU8698T
Make/Model: TOYOTA COROLLA
ALTIS CLASSIC 1.6 CVT

Estimate Repair Cost to Vehicle No :SKU8698T

Description	Quantity	List Price	Amount
		S\$	S\$
24 TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	450
25 TO SPRAY FRONT BUMPER,FRONT FENDER RH, FRONT DOOR RH, SIDE MIRROR RH	1 PC	800.00	650
		1,910.00	1,910.00
		Total	S\$ 8,604.55
		Add GST @ 7%	602.32
		Total Amount Payable	S\$ 9,206.87

TOTAL: SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED AND SIX AND CENTS EIGHTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: