



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:RICHARD

Ref: CC4/ASM21005459/Ups3q2  
Date: 30/08/2021  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHD 3102D	<b>Veh. Inspected</b>	SKS 6386S
<b>Policy No.</b>	VFX/P2419138	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M0397X	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	04/05/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ E 250CGI (A)	<b>c.c</b>	1796
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	WDD2120472A212458	<b>Colour</b>	BROWN
<b>Odometer</b>	141218 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/35Z R19	NEXEN	6 mm
<b>L/H Front Tyre</b>	225/35Z R19	NEXEN	6 mm
<b>R/H Rear Tyre</b>	265/30Z R19	NEXEN	6 mm
<b>L/H Rear Tyre</b>	265/30Z R19	NEXEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	29/04/2021	<b>Inspection Date</b>	05/05/2021
<b>Survey held at</b>	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**