



KLK: HSI/AU Tong
67423197

US \$ 3400

1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : AXA Insurance
(MOTOR CLAIM DEPARTMENT)

Email motor.survey@axa.com.sg

*not Arthur and
deal
morans
5/5/21
Take photos after repair
4 days.*

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SKS6386S Date: 04.05.2021
 Vehicle Model: MERCEDES E250 CGI Reg. Date: 01.10.2010
 Chassis No: WDD2120472A212458 D.O.A: 29.04.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Bootlid	1	\$ 2,263.00	\$ 2,263.00	R X
2	Bootlid Hinges	2	\$ 141.00	\$ 282.00	11 X
3	Bootlid Logo	1	\$ 69.40	\$ 69.40	11 X
4	Bootlid CC Emblem	1	\$ 62.50	\$ 62.50	11 X
5	Bootlid E250 Emblem	1	\$ 62.50	\$ 62.50	11 X
6	Bootlid CGI Emblem	1	\$ 62.50	\$ 62.50	11 X
7	Bootlid Number Plate Lamp	2	\$ 68.00	\$ 136.00	11 X
8	Bootlid Opener Switch	1	\$ 165.00	\$ 165.00	11 X
9	Bootlid Lamps	2	\$ 552.00	\$ 1,104.00	11 X
10	Bootlid Lamp Inner Seal	2	\$ 38.00	\$ 76.00	11 X
11	Bootlid Inner Lock	1	\$ 425.40	\$ 425.40	11 X
12	Bootlid Catch	1	\$ 52.50	\$ 52.50	11 X
13	Bootlid Stoppers	4	\$ 38.00	\$ 152.00	11 X
14	Bootlid Auto Close Switch	1	\$ 517.80	\$ 517.80	11 X
15	Bootlid Inner Trim Board - Lower	1	\$ 339.50	\$ 339.50	11 X
16	Bootlid Breakdown Sign Box	1	\$ 295.30	\$ 295.30	11 X
17	Bootlid Weatherstrip	1	\$ 232.20	\$ 232.20	11 X
18	Rear Bumper	1	\$ 1,645.30	\$ 1,645.30	1537.12 DO/SE ✓
19	Rear Bumper Chrome - Center	1	\$ 265.80	\$ 265.80	232.35 RE ✓
20	Rear Bumper Chrome - Side	2	\$ 205.50	\$ 411.00	161 X 2 = 322 RE ✓

C/F \$ 8,619.70



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
 Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 8,619.70

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
19	Rear Bumper Tow Cover	1	\$ 75.00	\$ 75.00	clw hpm X
20	Rear Bumper Attachment Lower Garnish 184-20	1	\$ 246.40	\$ 246.40	22/208 n
21	Rear Bumper Side Retainers top	2	\$ 88.50	\$ 177.00	! CRA
21	Rear Bumper Lower Attachment Retainers	2	\$ 85.60	\$ 171.20	17X
21	Rear Bumper Center Retainer	1	\$ 158.60	\$ 158.60	CRA
22	Rear Bumper Reverse Sensor - Original 198	4	\$ 380.00	\$ 1,520.00	Should lpc
23	Rear Bumper Reverse Sensor Holders	4	\$ 62.50	\$ 250.00	17X
24	Rear Bumper Reinforcement 545-22	1	\$ 588.30	\$ 588.30	34
24	Rear Bumper Reinforcement Garnish	1	\$ 285.60	\$ 285.60	25X
25	End Panel	1	\$ 817.30	\$ 817.30	2X
26	End panel Top Garnish	1	\$ 223.50	\$ 223.50	11X
27	Smartkey Antenna Sensor	1	\$ 189.20	\$ 189.20	22X
28	Spare Tyre Panel	1	\$ 920.80	\$ 920.80	22X
29	Spare Tyre Top Board	1	\$ 666.80	\$ 666.80	17X
30	Taillamp	2	\$ 672.30	\$ 1,344.60	22X
31	Taillamp Inner Seal	2	\$ 38.00	\$ 76.00	22X
32	Taillamp Railing Garnish	2	\$ 63.00	\$ 126.00	22X
33	Taillamp Panel	2	\$ 169.20	\$ 338.40	22X

Total For List Items: \$ 16,794.40
Less Spare Parts Discount (10%): \$ 1,679.44
Total: \$ 15,114.96
C/F \$ 15,114.96

VEHICLE INSPECTION ESTIMATE

SPECIAL NETT ITEMS B/F \$ 15,114.96

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Rear Bumper Plate W Casing	1	\$ 60.00	\$ 60.00	na X
2	Rear Bumper Clips 1set	1	\$ 30.00	\$ 30.00	na X
3	Bootlid Lamps 1set	2	\$ 25.00	\$ 50.00	na X
4	Bootlid Insulator Trim Clips 1set	1	\$ 30.00	\$ 30.00	na X
5	Rear Bumper Lower Cover Clips 1set	1	\$ 30.00	\$ 30.00	na X
6	Taillamp Clips 1set	2	\$ 25.00	\$ 50.00	na X
7	End Panel Top Garnish Clips	1	\$ 30.00	\$ 30.00	na X
8	End Panel Sealant	1	\$ 80.00	\$ 80.00	na X

Total For S/N Items: \$ 360.00

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,500.00	\$ 1,500.00	500
2	To respray affected areas	1	\$ 1,500.00	\$ 1,500.00	600
3	To tuff coat affected areas	1	\$ 100.00	\$ 100.00	na X
4	To conduct wiring check and repair	1	\$ 100.00	\$ 100.00	20
5	To replace/transfer bootlid mechanism	1	\$ 250.00	\$ 250.00	na X
6	To remove/refix rear interior upholstery	1	\$ 150.00	\$ 150.00	80
7	To straighten/realign rear exhaust silencer	1	\$ 200.00	\$ 200.00	na X
8	To remove/refix reverse camera	1	\$ 150.00	\$ 150.00	na X
9	To remove/refix reverse sensor and distance setting	1	\$ 150.00	\$ 150.00	50

Total For Labour: \$ 4,100.00

LKK Auto Consultants hence notify the Repairer of the following:

Grand Total: \$19,574.96

- To repair by the Repairer
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-33544
102
P-3019.04
S.N-30
L-1280
4299.0
202
3439