

Polyanth.

GBG80791C.

TP 111

Nissan NV200.

Xiao Tony

VSKYBAM20Z0146620.

Front Number Plate	crushed	30(SN) ✓
Front Number Plate Holder	dented	30(SN) ✓
Front Bumper	Deformed	589.70 ✓
Front Bumper Clips.	per	30(SN) ✓
Front Bumper Side Holder x02.	per	$35.2 \times 2 = 70.40$ ✓
Front Bumper Reinforcement.	per	614.90 X
Front Bumper Sponge.	crushed	125 ✓
Front Bumper Tow Cover.	per	28.20 X
Front Bumper Fog Lamp Cover. X2	per	$98.5 \times 2 = 197$ X
Front Apron Panel x02	crushed	$362.2 \times 2 = 724.40$ ✓
Front Apron Panel Clips.	per	40(SN) ✓
Front Grille	crushed	338 ✓
Front Grille Logo.	per	73.50 ✓
Front Grille Clips.	per	20(SN) ✓

GBG8079K.

Front Inner Air Guide x 02 ^{all on} 38 x 2 = 76 x

Bonnet ^{all in} 882 x

Bonnet Lock ^{all in} 78.70 x

Bonnet Moulding. ^{all in} 150(SN) x

Bonnet Advertisement Stickers. ^{all in} 350(SN) x

Handlep x 02 ^{all in} 615 x 2 = 1230 ✓

GBG8079K.

Rees Number Plate	$\left. \begin{matrix} 2 \text{ M} \\ 1 \text{ M} \end{matrix} \right\}$	30(SN) X
Rees Number Plate Holder.		30(SN) X
Rees Number Plate Lamp x 02	$\left. \begin{matrix} 1 \text{ M} \\ 1 \text{ M} \end{matrix} \right\}$	$80.2 \times 2 = 160.40$ X
Rees Bumper Dehorn		632.70 —
Rees Bumper Clips.	1 M	30(SN) —
Rees Bumper Side Holder x 02	1 M	$42 \times 2 = 84$ —
Rees Bumper Reflector x 02	Missing	$61.9 \times 2 = 123.80$ ✓
Rees Bumper Sponge.	Cracked	94 ✓
Rees End Panel Outer	$\left. \begin{matrix} 2 \text{ Dents} \\ 1 \text{ Dents} \end{matrix} \right\}$	345 —
Rees End Panel Inner.		776 —
Rees End Panel Sealant.	1 M	60(SN) —
Rees End Panel Top Garnish	Dehorn	175.70 ✓
Tail Lamp x 02	Cracked	$277 \times 2 = 554$ ✓
Reverse Sensor.	Damaged	280(SN)
		200(SN)

GBG 8079K.

Tailgate LH Dented	1469.60 ✓
Tailgate Lower Lock LH 2nd	115 ✓
Tailgate Upper Lock LH. 1st	119 ✓
Tailgate Outer Moulding LH. unclad	352 ✓
Tailgate Lower Hinge LH. xpm	107.20 x
Tailgate Inner Trim Board LH. Dented	193 ✓
Tailgate Inner Trim Board Clips LH. 1st	20(SN) ✓
Tailgate Glass Sealant LH. 1st	40(SN) ✓
Tailgate Surround Moulding LH. 1st	200(SN) 80(SN)
Tailgate Camera LH. 1st	480(SN) x.
Tailgate Advertisement Sticker LH. 1st	120(SN) 80(SN)
NV200 Wording. 2	141.70. ✓
Nissan Logo. 1st	64.90 ✓
70km/h Sticker. 1st	10(SN) ✓

GBG8079K.

Tailgate RH.	Dented	1102	✓
Tailgate lower lock RH	Dented	1115	✓
Tailgate upper lock RH.	MP	1119.	X
Tailgate lower hinge RH.	MP	107.20	X
Tailgate Lower Trim Board RH.	Rehd	145	✓
Tailgate Lower Trim Board clips RH.	MP	20(SN)	✓
Tailgate Glass Sealant RH.	MP	40(SN)	✓
Tailgate Surround Moulding RH.	MP	200(SN)	20(SN)
Tailgate Advertisement sticker RH.	MP	350(SN)	250(SN)
Spare Tyre Carrier.	MP	252	+
Tailgate Frame Weatherstripe	at	215	✓

9849.40

S.N: 1060

8864.46

G BG 8079 K.

Panel Beating (Front)

Spray Painting (Front)

Wiring (Front).

Panel Beating (Rear)

Spray Painting (Rear)

Wiring (Rear).

To spray buff coat

To remove reverse sensor

To remove rear camera.

To remove upholstery.

To transfer LH and RH tailgate fittings.

To remove LH and RH tailgate glasses.

~~800~~ 400

~~800~~ 200.

~~50~~ 30.

~~1200~~ 800

~~1200~~ 1000

~~50~~ 30

~~180~~ 80

~~100~~ 50

~~100~~ 50

~~150~~ 60

~~160~~ 100

~~160~~ 80.

2880

total: 12804.46

L/S: 102K.

11 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: