

GBF7722Z . 2016 June TP AXA
Nissan NV350 2488CC . Denise
JN1MC2E262006686

Front Bumper	torn	571.90. ✓
Front Bumper Clips	new	30 (SN) ✓
Front Bumper Side Holder LH.	cracked	161.70 ✓
Headlamp LH.	cracked	481.40 ✓
Radiator (Side) Cover.	cracked	84.40 ✓
Front LH Step Panel Garnish.	torn	214.50 ✓
Front LH Wheel Rim.	ALP new	200 (SN) x
Front LH Wheel Rim Cover.	cut	80 (SN) 60 (SN)
Sliding Door LH.	Regis	1325.40 x
Front LH Shock Absorber.	ALP new	282 x
Front LH Knuckle Arm.	Regis	525.20. ✓
Front LH Wheel Hub c/w Bearings.	new	382.50 ✓
Front LH Lower Arm.	ALP new	310.30 x
Front LH Door	Regis	1218 x
Front LH Door Company Address	Slick new	30 (SN) ✓

GBF 7722Z.

Panel Beating

Spray Painting

Wiring.

To dismantle front undercarriage.

To perform wheel alignment test.

To transfer front door fittings

~~800~~ 400

~~800~~ 700

~~50~~ 30

~~350~~ 200

~~150~~ 80

150. X

List: 2421.60

Labour: 1510

Len 10%: 2179.44

Total: 3809.44

S.N: 120

2/S: 23K

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3K.