



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: DAVID

Ref: CS/INC21005466/Uqf3n2

Date: 18/06/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 7219R	Veh. Inspected	SKP 1426J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1130380-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	05/05/2021

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD1173422N100692	Colour	GREY
Odometer	138791 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	01/05/2021	Inspect Date / Time	05/05/2021 ( 10:47 AM )
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**